

Vehicle Damage Assessment Report for [GBH6928T]

Estimate Created: 13/04/2023 15:16 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 13/04/2023 15:27 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Hiace
Engine Type			
License Plate Number	GBH6928T	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- VEHICLE MAKE AND MODEL: TOYOTA DYNA	Insurlogic 4 (13/04/2023 15:27)
- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK: CONCLUDED THE COST OF REPAIR AT \$1,950.00 WITH 4 WORKING DAYS	Insurlogic 4 (13/04/2023 15:27)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
Rear tailgate		1	1218.00	-25.00 %	913.50
LH tailgate hinge		1	192.00	-25.00 %	144.00
Tailgate sticker "Toyota"		1	190.60	-25.00 %	142.95
Rear corner panel rubber stopper LH		1	62.00	-25.00 %	46.50

Parts Subtotal 1,246.95

Materials

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
Rear tailgate sticker 70/KM/H		1.0	10.00	0.00 %	10.00
Rear car plate		1.0	35.00	0.00 %	35.00
Rear tailgate sticker 13 Pax		1.0	10.00	0.00 %	10.00
Rear pin (aluminium board)		1.0	40.00	0.00 %	40.00

Materials Subtotal 95.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
Panel beating	RnR	500.00	0.00 %	500.00
Anti-rust treatment on affected areas	RnR	30.00	0.00 %	30.00
To remove and replace rear tail gate check plate	RnR	100.00	0.00 %	100.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
Floor metal base panel	Medium	0.00	0.00 %	0.00
Rear corner lower panel L/R	Medium	0.00	0.00 %	0.00
Rear floor panel	Medium	0.00	0.00 %	0.00
Rear up step assy	Medium	0.00	0.00 %	0.00
Tailgate side lock latch RH/LH	Medium	0.00	0.00 %	0.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	500.00	0.00 %	500.00

Labor Rate	S\$ 50 / Hour	General Labor Subtotal	630.00
		Paint Labor Subtotal	500.00
		Labor Subtotal	1,130.00

Summary

	Repair Cost	2,471.95
	Discount(20 %)	(494.39)
		1,977.56
	Excess	(0.00)
	GST(0.00 %)	0.00
	Grand Subtotal	1,977.56