



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : UC712
Vehicle No. : GBH6928T
Make & Model : TOYOTA DYNA

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Rear tail gate <i>H/</i>		1218.00	
1	Rear tail gate hinges x4 @ \$272 <i>132 H/ (1pc)</i>		1088.00	192
1	Rear tail gate sticker "Toyota" <i>ne/</i>		380.00	190.60
2	Rear corner lower panel RH/LH @ 2*\$289 <i>repair</i>		578.00	X R
1	Rear corner lower panel rubber stopper RH/LH @ 2*\$62 <i>(1pc) mis/</i>		124.00	62
2	Rear tail gate side lock latch RH/LH @ 2*\$279 <i>repair</i>		558.00	X R
2	Rear tail gate lower latch RH/LH @ 2*\$261 <i>X nn</i>		522.00	X
2	Tail lamp RH/LH @ 2*\$371 <i>X nn</i>		742.00	X
2	Tail lamp panel RH/LH @ 2*\$310 <i>X nn</i>		620.00	X
1	Rear number plate holder plate <i>X nn</i>		391.00	X
1	Rear up step assy (Repair refer to labor)		0.00	
1	Rear Floor panel (Repair refer to labor)		0.00	
1	Floor metal base panel (Repair refer to labour)		0.00	
Part Items Total:			6221.00	
			-25%	-1555.25
				4665.75
SPECIAL NETT ITEMS				
1	Rear tail gate sticker 70km/h <i>ne/</i>		10 50.00	
1	Rear car plate <i>sun/</i>		35.00	
1	Rear reverse Sensor <i>ne? X nn</i>		200.00	X
1	Rear tail gate sticker 13pax <i>ne/</i>		10 50.00	
1	Rivet pin (aluminium board) <i>ne/</i>		60.00	X
1	Check plate <i>ne? X nn</i>		400.00	X
SN Items Total:			795.00	
Total Parts:			5460.75	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : UC712
Vehicle No. : GBH6928T
Make & Model : TOYOTA DYNA

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
LABOUR			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00	4500 500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	4500 500
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	60.00	X nn
4	To perform anti-rust treatment on affected areas	30.00	/
5	To remove and replace rear tail gate checker plate	300.00	100
6	To remove and replace rear reverse sensor	100.00	200 ? 40 X
Labour Total :		2090.00	
TOTAL (PARTS & LABOUR):		7550.75	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Panel
Ag 900 costs
4 days
Lp
21/03/23 @ 1230
Resy after repair