

Vehicle Details

Vehicle No.	Make / Model
SLH4126K	TOYOTA / COROLLA ALTIS CLASSIC 1.6 CVT
Vehicle Type :	Vehicle Attachment 1 :
R10 - Private Hire (Self-Drive) Motor Car	No Attachment
Vehicle Scheme :	Chassis No. :
Normal	MR053REH104561709
Propellant :	Engine No. :
Petrol	1ZRY344364
Motor No. :	Engine Capacity :
-	1598 cc
Power Rating :	Maximum Power Output :
-	90.0 kW (120 bhp)
Maximum Laden Weight :	Unladen Weight :
1640 kg	1205 kg
Year Of Manufacture :	Original Registration Date :
2016	01 Nov 2016
Lifespan Expiry Date :	COE Category :
-	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium :	COE Expiry Date :
\$50,991.00	31 Oct 2026
Road Tax Expiry Date :	PARF Eligibility Expiry Date :
30 Apr 2023	31 Oct 2026
Inspection Due Date :	Intended Transfer Date :
31 Oct 2023	31 Mar 2023
CO2 Emission :	CEV/VES Rebate Utilised Amount :

HIN LUNG WORKSHOP
BLK 1008 BUKIT MERAH LANE 3 #01-20
SINGAPORE 159722
TEL: 68583000 FAX: 64760075
GST REGN. NO. : M2-0065859-X
BUSINESS REGN NO. : 52861067L

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DATE : 15/3/2023

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD #16-01
SINGAPORE 068877
ATTN : MOTOR CLAIM DEPARTMENT

DEAR SIR,

ACCIDENT REPAIR ON : SLH4126K - TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT
INSURED : BOLT CAR LEASING PTE LTD
DATE OF ACCIDENT : 13/3/2023
YOUR INSURED VEH NO. : SHF92H

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED :-

REPLACEMENT OF PARTS

		SS	SS
1) FRONT BUMPER <i>de</i>	1 @	562.00	562.00
2) FRONT BUMPER SIDE RETAINER LH <i>Xnn</i>	1 @	90.40	90.40 X
3) FRONT BUMPER SIDE RETAINER RH <i>Xnn</i>	1 @	90.40	90.40 X
4) BUMPER CLIPS <i>re</i>	10 @	5.50	55.00
5) FRONT BUMPER ABSORBER <i>Xnn</i>	1 @	95.30	95.30 X
6) FRONT FENDER RH <i>st</i>	1 @	965.30	965.30 <i>968.70</i>
7) FRONT FENDER PROTECTOR RH <i>Xnn</i>	1 @	106.70	106.70 X
8) FRONT FENDER NAME <i>re</i>	1 @	37.70	37.70
9) FENDER CLIPS <i>re</i>	10 @	5.50	55.00
10) FRONT DOOR RH <i>repair</i>	1 @	1,335.20	1,335.20 XR
11) FRONT DOOR WEATHERSTRIP RH <i>Xnn</i>	1 @	191.00	191.00 X
12) ROCKER PANEL RH <i>Xnn</i>	1 @	981.50	981.50 X
13) MIRROR ASSY, OUTER REAR VIEW RH <i>cut</i>	1 @	1,335.50	1,335.50 <i>981.55</i>
14) MIRROR OUTER COVER <i>repair</i>	1 @	116.10	116.10 XR
15) LAMP, SIDE TURN SIGNAL RH <i>Xnn</i>	1 @	58.00	58.00 X

Rashid
Hp 90010068
6 days
4/8
17/03/23 @ 1100
Repair after repair

* SPECIAL NETT

16) WHEEL DISC <i>sea / s/n - 300 400</i>	1 @	2,133.00	2,133.00 <i>400 s/n</i>
---	-----	----------	-------------------------

LABOUR CHARGES

17) REPLACE NEW PARTS, REMOVE/REFIT ALL ATTACHMENT PARTS TO FACILIATE REPAIR	1,000.00	1,000.00 <i>600</i>
18) SPRAY PAINT ON THE EFFECTED AREAS WITH 2K PAINT	1,000.00	1,000.00 <i>700</i>
19) CHECK WIRING AND PROPER FUNCTIONING	100.00	100.00 <i>30</i>

NETT TOTAL BEFORE GST

1949.96 10,308.10

YOURS FAITHFULLY,

f 

(WORKSHOP MANAGER)

400.00
1330.00
3679.96
20%
2943.97

L/S - \$2,950 / 6 days