

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	OD/032023/6059
Policy No:	SP2000684732	Date of Loss:	13/03/2023
Vehicle Reg. No.:	SBE3800M	Driveable?	
Driver Age/Info:	59 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAN PECK SIAN JENNY	Contact No:	+6596730686
Driver:	LIANG TENG SOON HENRY		
Make/Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Vehicle Reg. Date:	29/12/2018
Vehicle Colour:	Brown		
Engine No:	FB20YE48472	Chassis No:	JF1SJ5KC5JG112788
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	REFER TO SKETCH		
Present Location:	VIN'S MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS

	Amount
Parts	4,433.00
Miscellaneous Items	0.00
Labour	1,360.00
Paintwork Labour	880.00
Towing	0.00
Gross Total (S\$)	6,673.00
+ GST 8.00% (S\$)	533.84
Nett Amount (S\$)	7,206.84

This claim is handled by: **RAYMOND TEO YUN LOONG**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Mar 2023)

Parts: M1-SUV SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Vin's Motor Pte Ltd/SBE3800M/15/03/2023 12:02

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper	0.00	0.00	*380.00 F
2	1		*Front bumper LH side retainer	0.00	0.00	*10.00 F
3	10		*Front bumper clips	0.00	0.00	*20.00 F
4	1		*Front LH headlamp	0.00	0.00	*1,700.00 F
5	1		*Front LH headlamp lower bracket	0.00	0.00	*30.00 F
6	1		*Front LH fender	0.00	0.00	*190.00 F
7	1		*Front LH fender inner shield	0.00	0.00	*80.00 F
8	10		*Front LH fender inner shield clips	0.00	0.00	*20.00 F
9	1		*Front LH fender triangle cover	0.00	0.00	*10.00 F
10	1		*Front LH fender insulator - Top	0.00	0.00	*20.00 F
11	1		*Front LH fender lower protector	0.00	0.00	*20.00 F
12	1		*Front LH door	0.00	0.00	*600.00 F
13	1		*Front LH door outer chrome moulding	0.00	0.00	*70.00 F
14	1		*Front LH door top pillar frame sticker	0.00	0.00	*40.00 F
15	1		*Front LH door top hinge	0.00	0.00	*30.00 F
16	1		*Front LH door lower hinge	0.00	0.00	*30.00 F
17	1		*LH side mirror signal light	0.00	0.00	*70.00 F
18	1		*Front LH sport rim	0.00	0.00	*550.00 F
19	1		*Front LH knuckle wheel bearing	0.00	0.00	*160.00 F

F=Franchise part.

Sub Total (\$\$)	4,030.00
+ Margin on L,N Items 10.00% (\$\$)	403.00
Total Parts (\$\$)	4,433.00

Vin's Motor Pte Ltd/SBE3800M/15/03/2023 12:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	TO SPRAY PAINTING	New	880.00
Labour Items			
2	To check wheel alignment	New	150.00
3	To remove and replace bearing	New	150.00
4	To reset headlamp system	New	280.00
5	TO REPAIR DAMAGES	New	780.00
Gross Labour Cost (S\$)			2,240.00