



AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM			
Claim Type:	OD (Own Damage)	Ref. No:	OD/032023/6059
Policy No:	SP2000684732	Date of Loss:	13/03/2023
Vehicle Reg. No.:	SBE3800M	Driveable?	
Driver Age/Info:	59 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAN PECK SIAN JENNY	Contact No:	+6596730686
Driver:	LIANG TENG SOON HENRY		
Make/Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Vehicle Reg. Date:	29/12/2018
Vehicle Colour:	Brown		
Engine No:	FB20YE48472	Chassis No:	JF1SJ5KC5JG112788
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8 S		
Description of Accident/Loss	REFER TO SKETCH		
Present Location:	VIN'S MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	4,433.00
Miscellaneous Items	0.00
Labour	1,360.00
Paintwork Labour	880.00
Towing	0.00
Gross Total (S\$)	6,673.00
+ GST 8.00% (S\$)	533.84
Nett Amount (S\$)	7,206.84

This claim is handled by: RAYMOND TEO YUN LOONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Mar 2023)

Parts: M1-SUV SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Vin's Motor Pte Ltd/SBE3800M/15/03/2023 12:02

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	CHECK PARTS	%Disc	%Depr	Amount
1	1		*Front bumper		0.00	0.00	*380.00 F
2	1		*Front bumper LH side retainer	CUT ✓	0.00	0.00	*10.00 F
3	10		*Front bumper clips	DIS ✓	0.00	0.00	*20.00 F
4	1		*Front LH headlamp		0.00	0.00	*1,700.00 F
5	1		*Front LH headlamp lower bracket		0.00	0.00	*30.00 F
6	1		*Front LH fender		0.00	0.00	*190.00 F
7	1		*Front LH fender inner shield		0.00	0.00	*80.00 F
8	10		*Front LH fender inner shield clips		0.00	0.00	*20.00 F
9	1		*Front LH fender triangle cover		0.00	0.00	*10.00 F
10	1		*Front LH fender insulator - Top	TH ✓	0.00	0.00	*20.00 F
11	1		*Front LH fender lower protector		0.00	0.00	*20.00 F
12	1		*Front LH door		0.00	0.00	*600.00 F
13	1		*Front LH door outer chrome moulding	CUT ✓	0.00	0.00	*70.00 F
14	1		*Front LH door top pillar frame sticker		0.00	0.00	*40.00 F
15	1		*Front LH door top hinge	SCR ✓	0.00	0.00	*30.00 F
16	1		*Front LH door lower hinge	SCR ✓	0.00	0.00	*30.00 F
17	1		*LH side mirror signal light		0.00	0.00	*70.00 F
18	1		*Front LH sport rim		0.00	0.00	*550.00 F
19	1		*Front LH knuckle wheel bearing	DM ✓	0.00	0.00	*160.00 F
Sub Total (\$\$)							4,030.00
+ Margin on L,N Items 10.00% (\$\$)							403.00
Total Parts (\$\$)							4,433.00

F=Franchise part.

Vin's Motor Pte Ltd/SBE3800M/15/03/2023 12:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO SPRAY PAINTING	New	600 800.00
<u>Labour Items</u>			
2	To check wheel alignment	New	150.00 XHH
3	To remove and replace bearing	New	150.00 XHH
4	To reset headlamp system	New	280.00
5	TO REPAIR DAMAGES	New	600 780.00
Gross Labour Cost (S\$)			2,240.00

Vin's Motor Pte Ltd/SBE3800M/15/03/2023 12:02. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR 5 DAYS

- NOT AUTHORISE
- EXCESS \$600
- P/P OR L/S REPAIR
- SURVEY BY EDWARD TEL 62563561
- RESURVEY BEFORE PAINT FOR P/P REPAIR.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: