

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002711/ANP3Q2**Date:** 14/06/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00108322203

Claimant Vehicle No : FBG8816A **Insured Vehicle No :** GBJ8294P

Date of Loss: 13/03/2023 Nature of Claim: TP Claim No: SNM23D201963/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBG8816A**

Make & Model: YAMAHA FZ8S, 779cc Engine No: N522E026440

Reg. Date: 21/12/2012 (Man. Year: 2012) Chassis No: JYARN251000004755

Colour: Grey Odometer: 127620 km

Engine Capacity: 779 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 120/70 R17 Rear Tyre Size: 180/55 R17

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,310.00	1,848.50	2,461.50	57.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	650.00	1,300.00	66.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,260.00	2,498.50	3,761.50	60.09
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	6,260.00	2,000.00	4,260.00	68.05

INSPECTION

Date of Assignment: 15/03/2023

Date Inspected: 16/03/2023 Inspected At: 25 KAKI BUKIT ROAD 4
#06-38 SYNERGY @ KB
SINGAPORE 417800
Repairer :Jd Motorsports Pte Ltd (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 13 Jun 2023)	
Parts:	N/A	YAMAHA FZ8S 779cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBG8816A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	370.00 F	*285.00 FL
2	1		*CLUTCH LEVER	Cut	180.00 F	*50.00 FL
3	1		*MIRROR	Cut	210.00 F	*65.00 FL
4	1		*SLIDER	Cut	200.00 F	*120.00 FL
5	1		*LEFT SIGNAL LIGHT	Cut	160.00 F	*65.00 FL
6	1		*HANDLE BAR BALANCER	Not Necessary	190.00 F	*- FL
7	1		*REAR BOX	Cut	450.00 FS	*350.00 FS
8	1		*TANK COVER	Not Necessary	380.00 F	*- FL
9	1		*FOOT GEAR LEVER	Not Necessary	180.00 F	*- FL
10	1		*RIDER FOOTREST LEFT	Cut	150.00 F	*60.00 FL
11	1		*PILLION FOOTREST LEFT	Cut	145.00 F	*60.00 FL
12	1		*REAR SWING ARM PADDLE BUSH	Cut	245.00 F	*60.00 FL
13	1		*HEAD COWLING	Cut	750.00 F	*480.00 FL
14	1		*FRONT FENDER	Cracked	360.00 F	*200.00 FL
15	1		*SIDE COVER LEFT	Deformed	220.00 F	*180.00 FL
16	1		*SIDE COVER EMBLEM	Necessary	120.00 F	*40.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,310.00	2,015.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	166.50
Total Parts (S\$)	4,310.00	1,848.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	FORK ALIGNMENT	New	250.00	100.00
2	SWING ARM REPAIR	New	300.00	50.00
3	RESRPAY COVER SET	New	650.00	250.00
4	RIM RESPRAY	New	250.00	0.00
5	LABOUR	New	500.00	250.00
Gross Labour Cost (S\$)			1,950.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >