

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0273/2023/EQ
DATE : 15-Mar-23
WIP : 12016

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON
YOUR INSURED VEH NO : SMN 1010 L**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR LIN SHIYANG
ADDRESS : 82 JALAN DAUD
#06-02
SINGAPORE 419592
TELEPHONE : HP +65 91157916
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : SD22V13211/VPC/R00/E00
VEHICLE NO : **SMS 9882 H**
MODEL CODE : AUDI A6 1.8 TFSI S-TRONIC
MODEL YEAR : 16/5/2017
ENGINE NO : CYG 017773
CHASSIS NO : WAUZZZ4G0HN062941
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Mar-23
PLACE OF ACCIDENT : TOA PAYOH WEST CARPARK T0130, RIGHT OUTSIDE SJI
INTERNATIONAL SCHOOL

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 9882 H

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	3,200.00	
4	TO RESPRAY FRONT BUMPER, BONNET AND RHS FRONT FENDER.	\$	3,000.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 7,272.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 9882 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 3,677.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 602.00	
3	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$ 151.00	
4	FRONT BUMPER ADAPTER - RH	1	\$ 45.00	
5	FRONT BUMPER CLOSING ELEMENT	1	\$ 251.00	
6	FRONT BUMPER SPOILER	1	\$ 1,115.00	
7	RADIATOR GRILLE	1	\$ 2,262.00	
8	RADIATOR GRILLE COVER	1	\$ 43.00	
9	FRONT PARKING AID SENSOR SUPPORT - LH / RH	2	\$ 158.00	
10	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 589.00	
11	FRONT BUMPER CHANNEL COVER - RH	1	\$ 61.00	
12	FRONT WHEEL SPOILER - RH	1	\$ 311.00	
13	FRONT BUMPER GUIDE PIECE - RH	1	\$ 45.00	
14	FRONT BUMPER BRACE - RH	1	\$ 36.00	
15	FRONT BUMPER FOAM FILLER PIECE	1	\$ 280.00	
16	FRONT BUMPER SIDE REINFORCEMENT	1	\$ 983.00	
17	FRONT BUMPER TOP COVER	1	\$ 145.00	
18	AIR CONDITIONER STICKER	1	\$ 24.00	
19	CAUTION SIGN STICKER	1	\$ 17.00	
20	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 544.00	
SUB TOTAL SPARE PARTS		:	\$ 11,339.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 9882 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SEAL RING	4	\$ 6.00	
22	HORN HIGH TONE - RH	1	\$ 226.00	
23	HORN BRACKET - RH	1	\$ 56.00	
24	FRONT FENDER - RH	1	\$ 1,653.00	
25	FRONT FENDER ATTACHMENT PARTS	1	\$ 113.00	
26	FRONT DOOR STONE GUARD FILM - RH	1	\$ 143.00	
27	FRONT FENDER BRACE - RH	1	\$ 114.00	
28	FRONT WHEEL HOUSING LINER - RH	1	\$ 335.00	
29	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 76.00	
30	FRONT DOOR STONE CHIP GUARD - RH	1	\$ 86.00	
31	DOUBLE-SIDED ADHESIVE TAPE	1	\$ 290.00	
32	ADHESIVE TAPE	1	\$ 63.00	
33	BONNET	1	\$ 5,861.00	
34	HEADLIGHT MOUNTING - RH	1	\$ 140.00	
35	HEADLIGHT - RH	1	\$ 10,735.00	
36	HEADLIGHT POWER MODULE	1	\$ 690.00	
37	HEADLIGHT POWER MODULE	1	\$ 643.00	
38	HEADLAMP FAN - RH	1	\$ 453.00	
39	HEADLIGHT HOSE - RH	1	\$ 41.00	
40	HEADLIGHT ADJUSTMENT ELEMENT	1	\$ 54.00	
SUB TOTAL SPARE PARTS		:	\$ 21,778.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 9882 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	HEADLIGHT COMPENSATING PIECE	2	\$ 94.00	
42	HEADLIGHT RANGE CONTROL MOTOR	1	\$ 361.00	
43	LIFT CYLINDER - RH	1	\$ 274.00	
44	LIFT CYLINDER HOSE	1	\$ 552.00	
45	LIFT CYLINDER COVER CAP - RH	1	\$ 68.00	
46	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 27.00	
47	RADIATOR AIR GUIDE - RH	1	\$ 276.00	
48	RADIATOR AIR GUIDE COVER - UPPER CENTRE	1	\$ 34.00	
49	FRONT NUMBER PLATE	S/N	\$ 60.00	
50	SUNDRIES		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 35,363.00	
TOTAL LABOUR CHARGES		:	\$ 7,272.00	
GRAND TOTAL		:	\$ 42,635.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT