

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23002723/RPA3Q2**Date:** 07/07/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No: SP2003907937

Claimant Vehicle No : GBF4981L**Insured Vehicle No :** SML7588H

Date of Loss: 10/02/2023

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBF4981L**

Make & Model: NISSAN NV200, 1.5 L MT ABS AIRBAG 2WD 6DR (M)

Engine No: K9KC400D055990

Reg. Date: 28/11/2016 (Man. Year: 2016)

Chassis No: VSKYBAM20Z0133311

Colour: White

Odometer: 133222 km

Engine Capacity: 1461 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14C

Rear Tyre Size: 175/70 R14C

Front Left Side: Comfort 6 mm

Rear Left Side: Comfort 6 mm

Front Right Side: Comfort 6 mm

Rear Right Side: Comfort 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	733.14	710.46	22.68	3.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	500.00	300.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,533.14	1,210.46	322.68	21.05
Approved Total (Overridden) (S\$)		950.00		
Nett Amount (S\$)	1,533.14	950.00	583.14	38.04
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 15/03/2023

Date Inspected: 16/03/2023

Inspected At:

ETHOZ Protect Pte Ltd (Bukit Batok)

30 Bukit Batok Crescent

Singapore 658075

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 07 Jul 2023)	
Parts:	N/A	NISSAN NV200 1.5 L MT ABS AIRBAG 2WD 6DR (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF4981L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Scratched	739.40 FN	*739.40 FN
2	1		*FRONT BUMPER RETAINER LH	Not Necessary	25.20 FN	*- FN
3	10		*FRONT BUMPER CLIPS	Necessary	50.00 FN	*50.00 FN
4	1		*FRONT FENDER LH (NPA)	Not Necessary	0.00 FN	*- FN
F=Franchise part. N=NettItemDisc.						
					Sub Total (S\$)	814.60 789.40
					- Nett Item Discount on N Items 10.00/10.00% (S\$)	81.46 78.94
					Total Parts (S\$)	733.14 710.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	400.00	300.00
2	TO RESPRAY AFFECTED AREAS	New	400.00	200.00
Gross Labour Cost (S\$)			800.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >