

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vonn Siow Lie Mien

Date: 21 Apr 2023

Preliminary Advice

Vehicle No	: FBK2806Y	Accident Date	: 11/02/2023
Make	: SUZUKI UH200AL5 BURGMAN	Policy No.	: 1001884999
Assignment Date	: 16/03/2023	Excess	: S\$300.00
Date of Inspection	: 16/03/2023	Est. Duration of Repair	: 0
Inspection At	: Glen Enterprise Pte Ltd		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	
Total	:S\$	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	3,800.00
COE / PARF Rebate	:S\$	1,396.00
Salvage Value	:S\$	
Margin for Repair	:S\$	2,404.00

Remarks

- () The vehicle is economical for repair
(X) The vehicle is not economical for repair
() Part-by-Part repair
() Lump Sum repair
- () The above survey was conducted on a 'without prejudice' basis.