

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER:

ECICS Limited (HQ)

** Repair key not working.*
Carpal

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC23P00043600	Date of Loss:	04/03/2023
Vehicle Reg. No.:	SJN4052G	Driveable?	
Driver Age/Info:	45 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAN CHUAN WOON	Contact No:	+6591091101
Driver:	TAN CHUAN WOON		

Make/Model:	TOYOTA WISH, 1.8 (A)	Vehicle Reg. Date:	13/02/2009
Vehicle Colour:	GREY		
Engine No:	1ZZ3226530	Chassis No:	JTDER12W003001831
Odometer:	333382 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair
(day) 6

Present Location: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS

	Amount
Parts	1,078.00
Miscellaneous Items	0.00
Labour	1,200.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,278.00
+ GST 8.00% (S\$)	182.24
Nett Amount (S\$)	2,460.24

This claim is handled by: JANICE CHANG SIEW YIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 15 Mar 2023)
Parts: M1-MPV **TOYOTA WISH 1.8 (A)** (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJN4052G)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER <i>repair</i>	0.00	0.00	*240.00 F
2	1		*FRT BUMPER LOWER SPOILER <i>repair</i>	0.00	0.00	*420.00 F
3	1		*FRT BUMPER RETAINER RH <i>X</i>	0.00	0.00	*35.00 F
4	10		*FRT BUMPER CLIPS <i>X</i>	0.00	0.00	*10.00 F
5	1		*FRT FENDER RH <i>bt</i>	0.00	0.00	*190.00 F
6	1		*FRT FENDER INNERSHIELD RH <i>?</i>	0.00	0.00	*75.00 F
7	10		*FRT FENDER INNERSHIELD CLIPS <i>re</i>	0.00	0.00	*10.00 F

F=Franchise part.

Sub Total (S\$)	980.00
+ Margin on L,N Items 10.00% (S\$)	98.00
Total Parts (S\$)	1,078.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK, WELD, REMOVE & FIX ABOVE PARTS	New	400 600.00
2	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREA	New	500 600.00
Gross Labour Cost (\$\$)			1,200.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pass
Hp 90010068

3 days

4/5

16/03/23 @ 1250

EXCESS: TBA

Repair

Resy after repair