



INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2000643955-01	Date of Loss:	13/03/2023
Vehicle Reg. No.:	SKB181U	Driveable?	
Driver Age/Info:	27 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NG TECK SENG	Contact No:	+6597617813
Driver:	NG YU HENG NICHOLAS		
Make/Model:	HONDA VEZEL, 1.5 1.5X CVT (A)	Vehicle Reg. Date:	02/12/2016
Vehicle Colour:	White		
Engine No:	L15B4030318	Chassis No:	RU11110314
Odometer:	1 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12		
Description of Accident/Loss	REFER TO GIA		
Remarks:	VEHICLE IS IN W/SHOP.		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	7,266.45
Miscellaneous Items	0.00
Labour	3,170.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	10,436.45
+ GST 8.00% (S\$)	834.92
Nett Amount (S\$)	11,271.37

This claim is handled by: **ANDY**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Mar 2023)

Parts: M1-SUV HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Falcon-Air Auto Services Pte Ltd/SKB181U/15/03/2023 09:26

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet	0.00	0.00	*420.00 F
2	1		*Bonnet hinge LH	0.00	0.00	*35.00 F
3	1		*Bonnet hinge RH	0.00	0.00	*35.00 F
4	1		*Bonnet Lock	0.00	0.00	*80.00 F
5	1		*Bonnet Lock Insulator Clip	0	0.00	*40.00 FS
6	1		*Radiator	0.00	0.00	*780.00 F
7	1		*Radiator Support Panel	0.00	0.00	*420.00 F
8	1		*Air Con Condenser	0.00	0.00	*420.00 F
9	1		*LH Headlamp	0.00	0.00	*950.00 F
10	1		*LH Headlamp Lower Bracket	0.00	0.00	*25.00 F
11	1		*Air Duct	0.00	0.00	*50.00 F
12	1		*Front Grille	0.00	0.00	*250.00 F
13	1		*Front Grille Chrome LH	0.00	0.00	*28.00 F
14	1		*Front Grille Chrome RH	0.00	0.00	*28.00 F
15	1		*Front Grille Logo	0.00	0.00	*18.00 F
16	1		*Front Grille Holder Centre	0.00	0.00	*60.00 F
17	1		*Front Grille Holder Clip	0	0.00	*40.00 FS
18	1		*Front Grille Top Holder LH	0.00	0.00	*18.00 F
19	1		*RH HeadlampLower Bracket	0.00	0.00	*25.00 F
20	1		*RH Headlamp	0.00	0.00	*950.00 F
21	1		*Horn	0.00	0.00	*45.00 F
22	1		*Front Bumper	0.00	0.00	*200.00 F
23	1		*Front Bumper Reinforcement	0.00	0.00	*185.00 F
24	1		*Front Bumper Side Bracket LH	0.00	0.00	*14.00 F
25	1		*Front Bumper Side Bracket RH	0.00	0.00	*14.00 F
26	1		*Front Bumper Lower Black	0.00	0.00	*148.00 F
27	1		*Front Bumper Lower Grille	0.00	0.00	*60.00 F
28	1		*Front Bumper Clip	0	0.00	*60.00 FS
29	1		*Front Grille Bracket	0.00	0.00	*165.00 F
30	1		*Fog Lamp Garnish LH	0.00	0.00	*22.00 F
31	1		*Fog Lamp LH	0.00	0.00	*145.00 F
32	1		*Air Guide LH	0.00	0.00	*50.00 F
33	1		*Front Fender Shield LH	0.00	0.00	*85.00 F
34	1		*Front Fender Shield Clip	0	0.00	*40.00 FS
35	1		*Air Resonator Box	0.00	0.00	*98.00 F
36	1		*Front Number Plate	0	0.00	*45.00 FS
37	1		*Front Engine Undercover	0.00	0.00	*100.00 F
38	1		*LH Front Fender	0.00	0.00	*200.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	6,348.00
+ Margin on L,N Items 15.00% (S\$)	918.45
Total Parts (S\$)	7,266.45

Falcon-Air Auto Services Pte Ltd/SKB181U/15/03/2023 09:26. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To check wiring and light system	New	50.00
2	To vacuum, reoil and recharge air con gas	New	120.00
3	To cut out, reweld radiator support panel, straighten RH front fender, front chasis, wheel house including replacement of parts	New	1,200.00
4	To spray paint bonnet, bonnet hinges, front chassis, front bumper, radiator support panel, LH/RH front fender, wheel house, RH front door	New	1,800.00
Gross Labour Cost (\$)			3,170.00

Falcon-Air Auto Services Pte Ltd/SKB181U/15/03/2023 09:26. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >