

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 27 Jun 2023

**Preliminary Advice**

Vehicle No	: SKB181U	Accident Date	: 13/03/2023
Make	: HONDA VEZEL	Policy No.	: SP2000643955-01
Assignment Date	: 16/03/2023	Excess	: S\$1,100.00
Date of Inspection	: 16/03/2023	Est. Duration of Repair	: 6
Inspection At	: FALCON-AIR AUTO SERVICES PTE LTD (SIN MING) 176 SIN MING DRIVE #01-06, SIN MING AUTOCARE SINGAPORE 575721		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,453.70 (inclusive supp \$17.25)
Revised Amount	:S\$	8,450.25
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,450.25
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	51,000.00
COE / PARF Rebate	:S\$	25,183.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,817.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :Kindly approve on supplementary.