



FALCON - AIR

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2000643955-01	Date of Loss:	13/03/2023
Vehicle Reg. No.:	SKB181U	Driveable?	
Driver Age/Info:	27 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NG TECK SENG	Contact No:	+6597617813
Driver:	NG YU HENG NICHOLAS		

Make/Model:	HONDA VEZEL, 1.5 1.5X CVT (A)	Vehicle Reg. Date:	02/12/2016
Vehicle Colour:	WHITE		
Engine No:	L15B4030318	Chassis No:	RU11110314
Odometer:	1 KM		

Paint Type:	
Total Loss?	<b>NO</b>
Est. Duration of Repair (day)	<del>12</del> 6

Description of Accident/Loss	REFER TO GIA
Remarks:	VEHICLE IS IN W/SHOP.
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (SIN MING)

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	7,266.45
Miscellaneous Items	0.00
Labour	3,170.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>10,436.45</b>
<b>+ GST 8.00% (S\$)</b>	<b>834.92</b>
<b>Nett Amount (S\$)</b>	<b>11,271.37</b>

**This claim is handled by: ANDY**

# REPAIR DETAILS

## Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 15 Mar 2023)  
**Parts:** M1-SUV      HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** Falcon-Air Auto Services Pte Ltd/SKB181U/15/03/2023 09:26  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet	0.00	0.00	✓*420.00 F BUC
2	1		*Bonnet hinge LH	0.00	0.00	BT ✓ *35.00 F SVC
3	1		*Bonnet hinge RH	0.00	0.00	BT ✓ *35.00 F SVC
4	1		*Bonnet Lock	0.00	0.00	nn X *80.00 F ?
5	1		*Bonnet Lock Insulator Clip	0	0.00	nett ✓*40.00 FS NEC
6	1		*Radiator	0.00	0.00	BT ✓ *780.00 F ?
7	1		*Radiator Support Panel	0.00	0.00	BR ✓ *420.00 F ?
8	1		*Air Con Condenser	0.00	0.00	BT ✓ *420.00 F ?
9	1		*LH Headlamp	0.00	0.00	✓*950.00 F CRA
10	1		*LH Headlamp Lower Bracket	0.00	0.00	BR ✓ *25.00 F ?
11	1		*Air Duct	0.00	0.00	✓*50.00 F CRA
12	1		*Front Grille	0.00	0.00	✓*250.00 F CRA
13	1		*Front Grille Chrome LH	0.00	0.00	✓*28.00 F CRA
14	1		*Front Grille Chrome RH	0.00	0.00	✓*28.00 F CRA
15	1		*Front Grille Logo	0.00	0.00	✓*18.00 F CNT
16	1		*Front Grille Holder Centre	0.00	0.00	40 ✓ *60.00 F CRA
17	1		*Front Grille Holder Clip	0	0.00	nett ✓*40.00 FS NEC
18	1		*Front Grille Top Holder LH	0.00	0.00	✓*18.00 F CRA
19	1		*RH Headlamp Lower Bracket	0.00	0.00	BR ✓ *25.00 F ?
20	1		*RH Headlamp	0.00	0.00	✓*950.00 F CRA
21	1		*Horn	0.00	0.00	*45.00 F SVC
22	1		*Front Bumper	0.00	0.00	✓*200.00 F DIS
23	1		*Front Bumper Reinforcement	0.00	0.00	BT ✓*185.00 F ?
24	1		*Front Bumper Side Bracket LH	0.00	0.00	✓ *14.00 F DIS
25	1		*Front Bumper Side Bracket RH	0.00	0.00	✓*14.00 F DIS
26	1		*Front Bumper Lower Black	0.00	0.00	140 ✓*148.00 F CRA
27	1		*Front Bumper Lower Grille	0.00	0.00	✓*60.00 F CRA
28	1		*Front Bumper Clip	0	0.00	nett ✓ *60.00 FS NEC
29	1		*Front Grille Bracket	0.00	0.00	BR ✓*165.00 F ?
30	1		*Fog Lamp Garnish LH	0.00	0.00	✓ *22.00 F CRA
31	1		*Fog Lamp LH	0.00	0.00	✓*145.00 F CRA
32	1		*Air Guide LH	0.00	0.00	nn X *50.00 F ?
33	1		*Front Fender Shield LH	0.00	0.00	TN ✓*85.00 F ?
34	1		*Front Fender Shield Clip	0	0.00	nett ✓*40.00 FS ?
35	1		*Air Resonator Box	0.00	0.00	✓ *98.00 F CRA
36	1		*Front Number Plate	0	0.00	nett ✓ *45.00 FS CRA
37	1		*Front Engine Undercover	0.00	0.00	BR ✓*100.00 F ?
38	1		*LH Front Fender	0.00	0.00	*200.00 F LR

F=Franchise part. S=SpcNett.

Falcon-Air Auto Services Pte Ltd/SKB181U/15/03/2023 09:26. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

Supp - Bracket L Fog lamp \$15.00 ✓ BR



# Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

# Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	To check wiring and light system	New	50.00 30
2	To vacuum, reoil and recharge air con gas	New	120.00 100
3	To cut out, reweld radiator support panel, straighten RH front fender, front chassis, wheel house including replacement of parts	New	1,200.00 600
4	To spray paint bonnet, bonnet hinges, front chassis, front bumper, radiator support panel, LH/RH front fender, wheel house, RH front door	New	1,800.00 900
<b>Gross Labour Cost (S\$)</b>			<b>3,170.00</b>

Falcon-Air Auto Services Pte Ltd/SKB181U/15/03/2023 09:26. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

## FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862  
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110  
Website: www.falconair.com.sg Email: email@falconair.com.sg

- Not authorise.

- Excess : \$1100

- L/S or P/P repair ?

- Survey by Edward (6256 3561)

- Re-survey before paint for P/P repair.

- 6 days to repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: