



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC23002745/Uvy3e2 Date: 12/04/2023 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	GBG 7629E
	Policy No.	Z22VC05013712	Coverage (\$)	0.00
	Claim No.	22/23/23/VC05/027107	Excess (\$)	600.00
	Assign From	GERALD POH	Assign Date	16/03/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JTFAT35Y50K209001	Colour	SILVER
	Odometer	275525 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	GOFORM	6 mm
	L/H Front Tyre	195 R15	GOFORM	6 mm
	R/H Rear Tyre	155 R12 (D)	DURAMAX	6/6 mm
	L/H Rear Tyre	155 R12 (D)	DURAMAX	6/6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR CANOPY. THE CHASSIS FRAME AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/03/2023	Inspection Date	16/03/2023
	Survey held at	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711		
5a. Remarks				
	A)THE MARKET VALUE IS S\$58,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	