



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 1868L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)	
<b>REPLACEMENT OF PARTS</b>					
1	REAR LH SIDE RAILING (SN)	TO REPAIR SEE LABOUR	650.00	-	
			650.00	-	
<b>LABOUR</b>					
	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS. INCLUSIVE OF THE REPAIR OF REAR LH SIDE RAILING. (50%)		300.00	150.00	
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTECD AREAS. (\$200.00)(50%)	300.00	100.00		
			600.00	250.00	
<b>GRAND TOTAL</b>			<b>1,250.00</b>	<b>250.00</b>	
<b>RECOMMENDED COST OF REPAIRS</b>				<b>250.00</b>	

Report Ref No. CS/FCI23002747/Uvy3e2

**MARKET VALUE: \$38,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$7,720.00=NETT VALUE: \$30,280.00**

**CHUA KANG SENG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**