



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD  
16 RAFFLES QUAY  
#42-01 HONG LEONG BUILDING  
SINGAPORE 048581

Ref: CS/FCI23002747/Uvy3

Date: 16/03/2023

Code: FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SBS 6494U	<b>Veh. Inspected</b>	YN 1868L
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D23000605MFBP	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	CAROLINE CABRERA	<b>Assign Date</b>	16/03/2023

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>		<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>		<b>Colour</b>	
<b>Odometer</b>	-	<b>Steering</b>	
<b>Brakes</b>		<b>Modification</b>	
<b>General</b>			

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>			mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>			mm
<b>L/H Rear Tyre</b>			mm

### 4. Description of Damages

--

### 5. General Information

<b>Accident Date</b>	17/02/2023	<b>Inspection Date</b>	16/03/2023
<b>Survey held at</b>	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--