



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
 #08-1339 Singapore 470130
 Tel: 9450 7920
 * zoomautowerks@gmail.com

not actual
all
10/3/23
2/s \$6800/
4 days!

20 March 2023

REG NO.: SLM 4543 M
 MAKE/MODEL: ALFA ROMEO GINLIETTA

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(S\$)
LIST ITEMS		
1	Front door -RH <i>Body ID/seat</i>	3100 \$ 3,567.40 ✓
2	Front door hinges <i>11</i>	\$ 294.20 X
1	Front door inner board <i>su</i>	\$ 855.00 X
1	Front door inner handle <i>11</i>	\$ 598.00 X
1	Front door lock <i>suc</i>	\$ 325.00 X
1	Front door lock catch <i>11</i>	\$ 285.00 X
1	Front door outer handle <i>11</i>	\$ 560.00 X
1	Front door regulator with motor <i>11</i>	\$ 956.00 X
1	Front door rubber <i>all</i>	320 \$ 560.00 ✓
1	Front door side mirror <i>n</i>	\$ 925.00 X
1	Front bumper <i>n</i>	\$ 1,950.00 X
1	Front bumper side retainer <i>11</i>	\$ 105.00 X
1	Front fender -RH <i>n</i>	\$ 874.70 X
1	Front fender signal lamp <i>11</i>	\$ 110.00 X
1	Rear door -RH <i>Body ID/seat</i>	\$ 2,895.65 ✓
1	Rear door regulator with motor <i>11</i>	\$ 880.00 X
1	Rear door rubber <i>all</i>	300 \$ 480.00 ✓
1	Rear bumper <i>n</i>	\$ 1,826.00 X
1	Rear bumper side retainer <i>11</i>	\$ 105.00 X
1	Rear fender <i>n</i>	\$ 2,189.53 X
1	Rear shock absorber <i>11</i>	\$ 483.56 X
1	Rear knuckle arm <i>11</i>	\$ 510.90 X
1	Rear lower arm <i>11</i>	\$ 326.50 X
1	Rear top arm <i>11</i>	\$ 213.59 X
1	Rear trailing arm <i>11</i>	\$ 896.52 X
		\$ 22,772.55
	Less 10%	\$ 2,277.26
		\$ 20,495.30
SPECIAL NETT ITEMS		
1	Front wheel rim <i>11</i>	\$ 1,000.00 X
1	Front tyre <i>11</i>	\$ 450.00 X
1	Rear wheel rim <i>merged</i>	\$ 1,000.00 600
1	Rear tyre <i>su</i>	\$ 450.00 X
		\$ 2,900.00

S/N

LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$	80.00
2	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00
3	To remove and refit inner garnishes.	\$	180.00
4	To remove and refit rear undercarriage.	\$	11 400.00
5	To conduct wheel alignment.	\$	180.00
6	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.	\$	500.00
7	To apply undercoating.	\$	150.00
8	Panel beating.	\$	1,600.00
9	To re-spray painting on the affected areas.	\$	1,500.00
10	To diagnose erase fault memory after repair.	\$	300.00
		\$	<u>4,970.00</u>

GRAND TOTAL :

\$ 28,365.30

LRV Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2-6615-65
102
59574.08
600
2030
5884.08