



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: NATALIE LEE

Ref: CS/INC23002751/Sqy3m4

Date: 18/07/2023

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBN 9826C	Veh. Inspected	SMC 2415D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1213288-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	16/03/2023

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MR053REH604581296	Colour	BLACK
Odometer	82148 KM	Steering	MISALIGNED
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55R16	FIRENZA	5 mm
L/H Front Tyre	205/55R16	FIRENZA	5 mm
R/H Rear Tyre	205/55R16	FIRENZA	5 mm
L/H Rear Tyre	205/55R16	FIRENZA	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/03/2023	Inspect Date / Time	17/03/2023 (04:00 PM)
Survey held at	56 LOYANG WAY, #04-04 LOYANG ENTERPRISE BUILDING		
Repairer	AP AUTOMOTIVE SERVICES PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**