

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 20.03.2023

TO : EQ MOTOR CLAIMS DEPTS
VEHICLE NO : PC4884J
MODEL : TOYOTA HIACE COMMUT
DATE OF ACCIDENT : 15.03.2023
TIME OF ACCIDENT : 09:00 HOURS

Xin Yu.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR SIDE PANEL LH <i>Dented</i>	1	\$ 1,984.00	\$ 1,984.00
2	REAR SIDE INNER LOWER PANEL LH <i>Repair</i>	1	\$ 654.20	\$ 654.20
3	REAR SHOCK ABSORBER LH <i>New</i>	1	\$ 439.00	\$ 439.00
4	REAR WHEEL HUP LH <i>New</i>	1	\$ 390.00	\$ 390.00
5	REAR WHEEL HUP BEARING LH <i>New</i>	1	\$ 187.00	\$ 187.00
6	REAR BUMPER <i>Dented</i>	1	\$ 479.00	\$ 479.00
7	REAR BUMPER SIDE RETAINER <i>New</i>	2	\$ 55.00	\$ 110.00
8	TAIL LAMP <i>LH cut</i>	2	\$ 390.00	\$ 780.00
9	TAILLAMP LOWER GARNISH <i>Repair</i>	2	\$ 167.00	\$ 334.00
10	TAILLAMP LOWER GARNISH RETAINER <i>New</i>	2	\$ 65.00	\$ 130.00

2649
198675

TOTAL PRICE	\$ 5,487.20
LESS 25%	\$ 1,371.80
SUB TOTAL PRICE	\$ 4,115.40

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00
2	REAR BUMPER LOWER SPOILER(SPECAIL TYPE) <i>Dented</i>	1	\$ 1,800.00	\$ 1,800.00
3	REAR SIDE PANEL SEALANT LH <i>New</i>	1	\$ 150.00	\$ 150.00
4	REAR SIDE INNER LOWER PANEL LH SEALANT <i>New</i>	1	\$ 80.00	\$ 80.00
5	REAR SIDE PANEL INNER TRIM CLIP LH (SET) <i>New</i>	1	\$ 60.00	\$ 60.00

TO : EQ MOTOR CLAIMS DEPTS
 VEHICLE NO : PC4884J
 MODEL : TOYOTA HIACE COMMUT
 DATE OF ACCIDENT : 15.03.2023
 TIME OF ACCIDENT : 09:00 HOURS

6	REAR SIDE PANEL GLASS SEALANT LH <i>3 New</i>	1	\$ 80.00	\$ 80.00	<i>40</i>
7	REAR SIDE PANEL GLASS INNER SEAL LH	1	\$ 60.00	\$ 60.00	<i>30</i>
8	TAIL LAMP CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	<i>10</i>
9	TAILLAMP LOWER GARNISH CLIP (SET) <i>New</i>	1	\$ 40.00	\$ 40.00	<i>X</i>
10	SPORT RIM WHEEL <i>Bent</i>	1	\$ 1,200.00	\$ 1,200.00	<i>450</i>
11	REAR TYRE <i>New</i>	1	\$ 480.00	\$ 480.00	<i>X</i>
12	BRAKE OIL <i>New</i>	1	\$ 80.00	\$ 80.00	<i>X</i>

1550

TOTAL \$ 4,170.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING AND REPLACE PARTS	\$ 2,200.00	<i>600</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	<i>700</i>
3	WIRNING, BULB CHECKING	\$ 250.00	<i>30</i>
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 650.00	<i>80</i>
5	REMOVE AND REFIX SLIDING DOOR LH	\$ 180.00	<i>X</i>
6	CONDUCT WATER LEAKAGE TEST	\$ 120.00	<i>X</i>
7	REMOVE AND REFIX SIDE PANEL GLASS LH	\$ 200.00	<i>60</i>
8	REMOVE AND REFIX LINING & SEATS	\$ 480.00	<i>X</i>
9	REMOVE REFIX REAR UNDERCARRIAGE	\$ 480.00	<i>X</i>

TO : EQ MOTOR CLAIMS DEPTS
VEHICLE NO : PC4884J
MODEL : TOYOTA HIACE COMMUT
DATE OF ACCIDENT : 15.03.2023
TIME OF ACCIDENT : 09:00 HOURS

10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	--	-----------	---

TOTAL \$ 6,540.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,285.40
TOTAL LABOUR COST : \$ 6,540.00
TOTAL REPAIR COST : \$ 14,825.40

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP:8297 9787

total: 5006.75
L/S: AK ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: