



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                               |  |   |                            |                |
|---|--|---|----------------------------|----------------|
| SOMPO INSURANCE SINGAPORE PL<br>50 RAFFLES PLACE #03-03<br>SINGAPORE LAND TOWERSINGAPORE 048623 |  |   | Ref: CS/SMO23002755/Uny3e2 |                |
|   |  |   | Date: 19/05/2023           |                |
|   |  |   | Code: SMO                  |                |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>   |  |   |                            |                |
|   | <b>Insured Veh.</b>  | SLS 7230P   | <b>Veh. Inspected</b>      | FBT 4731T      |
|   | <b>Policy No.</b>  | D22MTPV01014536   | <b>Coverage (\$)</b>       | 0.00           |
|   | <b>Claim No.</b>   | CMTD2300979/SYH   | <b>Excess (\$)</b>         | 0.00           |
|   | <b>Assign From</b>   | BETTY WONG  | <b>Assign Date</b>         | 16/03/2023     |
| <b>2. Vehicle Particulars &amp; Condition</b>   |  |   |                            |                |
|   | <b>Make &amp; Model</b>  | YAMAHA JUPITER MX   | <b>c.c</b>                 | 134            |
|   | <b>Engine No.</b>  | HIDDEN  | <b>Year of Reg.</b>        | 2013           |
|   | <b>Chassis No.</b>   | MH350C004DK579231   | <b>Colour</b>              | BLACK          |
|   | <b>Odometer</b>  | 91032 KM  | <b>Steering</b>            | IN ORDER       |
|   | <b>Brakes</b>  | IN ORDER  | <b>Modification</b>        | SPORTS RIM     |
|   | <b>General</b>   | GOOD  |                            |                |
| <b>3. Conditions of Tyres</b>   |  |   |                            |                |
|   |  | <b>Size</b>   | <b>Make</b>                | <b>Balance</b> |
|   | <b>R/H Front Tyre</b>  | 70-90-17  | PIRELLI                    | 6 mm           |
|   | <b>L/H Front Tyre</b>  |   |                            | mm             |
|   | <b>R/H Rear Tyre</b>   | 90-80-17  | PIRELLI                    | 6 mm           |
|   | <b>L/H Rear Tyre</b>   |   |                            | mm             |
| <b>4. Description of Damages</b>  |  |   |                            |                |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.<br>DAMAGES SEE DETAILS.  |   |                            |                |
| <b>5. General Information</b>   |  |   |                            |                |
|   | <b>Accident Date</b>   | 06/03/2023  | <b>Inspection Date</b>     | 17/03/2023     |
|   | <b>Survey held at</b>  | EVERBRIGHT MOTOR CYCLES CO<br>53 PAYA UBI INDUSTRIAL PARK #01-10/12 UBI AVENUE 1 SINGAPORE 408934 |                            |                |
| <b>5a. Remarks</b>  |  |   |                            |                |
|   | A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS.<br>B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                            |                |
| <b>5b. Estimate Days of Repair</b>  |  |   |                            |                |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR:  |   | <b>3 Working Days</b>      |                |