

Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 24/04/	Cust No/Name	/NG MEIQI, JOLENE
	Reg No/Reg Date	SMH1495C / 14/01/201
	Date In/Mileage	24/04/2019/ 3873
	Chassis No	MMBSTA13AKH000542
	Engine No	3A92UHL8706
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	06/05/2019/ 18:43		265 / AndreChow	39065			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2700.00
RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, RH FRONT FENDER, LH FRONT FENDER, REPAIR RH FRONT DOOR, REPAIR LH FRONT DOOR								
E PNT88000								100.00
REMOVE AND INSTALL A/CON CONDENSER AND RADIATOR TO FACILITATE REPAIR WORK								
A 55900099								80.00
TOP UP A/CON GAS AND CHECK A/CON SYSTEM								
E PNT98000								2800.00
PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER FACE, FRONT BODY KITS, RH FRONT FENDER, LH FRONT FENDER, RH FRONT DOOR, LH FRONT DOOR AND AFFECTED PORTION								
M SUNDRY								80.00
APPLY BODY SEALANT								
A 54900099								30.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								
M SUNDRY								80.00
PERFORM RUST PREVENTION								
M SUNDRY								40.00
APPLY SEALANT FOR FRONT BODY KITS								
M SUNDRY								20.00
SUNDRIES								
E PNT88000								500.00
VEHICLE REPAIR ON O-LINER (??) PHOTO								
S SPECIALISTJOB								50.00
TO SUPPLY ONE PC OF FRONT LICENSE PLATE RECTANGULAR & BLACK								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST (REPORT) TBA								
X EXC								-300.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

## ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892  24/04/	Cust No/Name	/NG MEIQI, JOLENE
	Reg No/Reg Date	SMH1495C / 14/01/201
	Date In/Mileage	24/04/2019/ 3873
	Chassis No	MMBSTA13AKH000542
	Engine No	3A92UHL8706
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
KAX00008	Credit	06/05/2019/ 18:43		265 / AndreChow	39065	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
INSURANCE POLICY EXCESS						
X	PANEL ASSY,FR END		1.00	1045.00	23.00	804.65
X	PANEL,HEADLAMP SUPPORT,UPR		1.00	65.00	23.00	50.05
X	CONDENSER ASSY,A/C REFRIGE		1.00	750.00	23.00	577.50
X	PANEL,AIR GUIDE		1.00	111.00	23.00	85.47
X	RADIATOR ASSY		1.00	958.00	23.00	737.66
X	TANK ASSY,RADIATOR COND		1.00	41.00	23.00	31.57
X	FAN,COOLING,LH		1.00	76.00	23.00	58.52
X	SHROUD,COOLING FAN		1.00	129.00	23.00	99.33
X	LLC 4L		1.00	26.00	23.00	20.02
X	PANEL,AIR GUIDE,RH		1.00	11.00	23.00	8.47
X	PANEL,AIR GUIDE,LH		1.00	11.00	23.00	8.47
X	CLIP,FR BUMPER		10.00	3.00	23.00	23.10
X	TANK,WINDSHIELD WASHER		1.00	73.00	23.00	56.21
X	GASKET,W/SHLD WASHER MOTOR		1.00	4.00	23.00	3.08
X	DUCT,A/CLNR INTAKE		1.00	130.00	23.00	100.10
X	HOOD		1.00	726.00	23.00	559.02
X	HINGE,HOOD,LH		1.00	55.00	23.00	42.35
X	HINGE,HOOD,RH		1.00	55.00	23.00	42.35
X	INSULATOR,HOOD		1.00	175.00	23.00	134.75
X	LATCH,HOOD		1.00	68.00	23.00	52.36
X	CLIP,HOOD LOCKING		1.00	4.00	23.00	3.08
X	CLIP,HOOD LOCKING		1.00	3.00	23.00	2.31
X	FENDER,FR LH		1.00	492.00	23.00	378.84
X	FENDER,FR RH		1.00	492.00	23.00	378.84
X	CLIP,FENDERSHIELD		10.00	3.00	23.00	23.10
X	EMBLEM ECO		2.00	34.00	00.00	68.00
X	HEADLAMP ASSY,LH		1.00	654.00	23.00	503.58
X	HEADLAMP ASSY,RH		1.00	654.00	23.00	503.58
X	GRILLE,RADIATOR		1.00	548.00	23.00	421.96
X	BRACKET,FR BUMPER,LH		1.00	13.00	23.00	10.01
X	BRACKET,FR BUMPER,RH		1.00	13.00	23.00	10.01
X	GRILLE,FR UNDER		1.00	163.00	23.00	125.51

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 24/04/	<table border="1"> <tr> <td>Cust No/Name</td><td>/NG MEIQI, JOLENE</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMH1495C / 14/01/201</td></tr> <tr> <td>Date In/Mileage</td><td>24/04/2019/ 3873</td></tr> <tr> <td>Chassis No</td><td>MMBSTA13AKH000542</td></tr> <tr> <td>Engine No</td><td>3A92UHL8706</td></tr> <tr> <td>Make/Model</td><td>MIT/19MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>U01 / BK BLACK</td></tr> </table>	Cust No/Name	/NG MEIQI, JOLENE	Reg No/Reg Date	SMH1495C / 14/01/201	Date In/Mileage	24/04/2019/ 3873	Chassis No	MMBSTA13AKH000542	Engine No	3A92UHL8706	Make/Model	MIT/19MY ATTRAGE 1.2 CVT	Colour/Trim	U01 / BK BLACK
Cust No/Name	/NG MEIQI, JOLENE														
Reg No/Reg Date	SMH1495C / 14/01/201														
Date In/Mileage	24/04/2019/ 3873														
Chassis No	MMBSTA13AKH000542														
Engine No	3A92UHL8706														
Make/Model	MIT/19MY ATTRAGE 1.2 CVT														
Colour/Trim	U01 / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	06/05/2019/ 18:43		265 / AndreChow	39065		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
X	COVER,HEADLAMP SUPT PANEL			1.00	62.00	23.00	47.74
X	FACE,FR BUMPER			1.00	696.00	23.00	535.92
X	MARK,THREE-DIA			1.00	51.00	23.00	39.27
X	UNPAINTED BODYKITS			1.00	1110.00	20.00	888.00
X	COVER,AIR CLEANER			1.00	44.00	23.00	33.88
Estimate							

Confirm & accepted by

7% GST on	Nett 13768.66	13,768.66
		963.81
Total Payable		14,732.47

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.