



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/NG MEIQI, JOLENE
24/04/	Reg No/Reg Date	SMH1495C / 14/01/201
	Date In/Mileage	24/04/2019/ 3873
	Chassis No	MMBSTA13AKH000542
	Engine No	3A92UHL8706
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX0000S	Credit	06/05/2019/ 18:43		265 / AndreChow	39065		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							2700.00
RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, RH FRONT FENDER, LH FRONT FENDER, REPAIR RH FRONT DOOR, REPAIR LH FRONT DOOR							
E PNT88000							100.00
REMOVE AND INSTALL A/CON CONDENSER AND RADIATOR TO FACILITATE REPAIR WORK							
A 55900099							80.00
TOP UP A/CON GAS AND CHECK A/CON SYSTEM							
E PNT98000							2800.00
PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER FACE, FRONT BODY KITS, RH FRONT FENDER, LH FRONT FENDER, RH FRONT DOOR, LH FRONT DOOR AND AFFECTED PORTION							
M SUNDRY							80.00
APPLY BODY SEALANT							
A 54900099							30.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							
M SUNDRY							80.00
PERFORM RUST PREVENTION							
M SUNDRY							40.00
APPLY SEALANT FOR FRONT BODY KITS							
M SUNDRY							20.00
SUNDRIES							
E PNT88000							X 500.00
VEHICLE REPAIR ON O-LINER (??) PHOTO (no photo) NAX							
S SPECIALISTJOB							50.00
TO SUPPLY ONE PC OF FRONT LICENSE PLATE RECTANGULAR & BLACK							
A 10028901							120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST (REPORT) TBA							
X EXC							-300.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

### ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /NG MEIQI, JOLENE Reg No/Reg Date SMH1495C / 14/01/201 Date In/Mileage 24/04/2019/ 3873 Chassis No MMBSTA13AKH000542 Engine No 3A92UHL8706 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim U01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	06/05/2019/ 18:43		265 / AndreChow	39065
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
INSURANCE POLICY EXCESS					
X PANEL ASSY,FR END <i>bt</i>		1.00	1045.00	23.00	804.65
X PANEL,HEADLAMP SUPPORT,UPR <i>bt</i>		1.00	65.00	23.00	50.05
X CONDENSER ASSY,A/C REFRIGE <i>bt</i>		1.00	750.00	23.00	577.50
X PANEL,AIR GUIDE <i>ca</i>		1.00	111.00	23.00	85.47
X RADIATOR ASSY <i>bt</i>		1.00	958.00	23.00	737.66
X TANK ASSY,RADIATOR COND <i>de</i>		1.00	41.00	23.00	31.57
X FAN,COOLING,LH <i>ca</i>		1.00	76.00	23.00	58.52
X SHROUD,COOLING FAN <i>ca</i>		1.00	129.00	23.00	99.33
X LLC 4L <i>re</i>		1.00	26.00	23.00	20.02
X PANEL,AIR GUIDE,RH <i>ca</i>		1.00	11.00	23.00	8.47
X PANEL,AIR GUIDE,LH <i>ca</i>		1.00	11.00	23.00	8.47
X CLIP,FR BUMPER <i>re</i>		10.00	3.00	23.00	23.10
X TANK,WINDSHIELD WASHER <i>de</i>		1.00	73.00	23.00	56.21
X GASKET,W/SHLD WASHER MOTOR <i>re</i>		1.00	4.00	23.00	3.08
X DUCT,A/CLNR INTAKE <i>ca</i>		1.00	130.00	23.00	100.10
X HOOD <i>bt</i>		1.00	726.00	23.00	559.02
X HINGE,HOOD,LH <i>bt</i>		1.00	55.00	23.00	42.35
X HINGE,HOOD,RH <i>bt</i>		1.00	55.00	23.00	42.35
X INSULATOR,HOOD <i>de</i>		1.00	175.00	23.00	134.75
X LATCH,HOOD <i>bt</i>		1.00	68.00	23.00	52.36
X CLIP,HOOD LOCKING <i>re</i>		1.00	4.00	23.00	3.08
X CLIP,HOOD LOCKING <i>re</i>		1.00	3.00	23.00	2.31
X FENDER,FR LH <i>bt</i>		1.00	492.00	23.00	378.84
X FENDER,FR RH <i>bt</i>		1.00	492.00	23.00	378.84
X CLIP,FENDERSHIELD <i>re</i>		10.00	3.00	23.00	23.10
X EMBLEM ECO <i>re</i>		2.00	34.00	00.00	68.00
X HEADLAMP ASSY,LH <i>ca</i>		1.00	654.00	23.00	503.58
X HEADLAMP ASSY,RH <i>ca</i>		1.00	654.00	23.00	503.58
X GRILLE,RADIATOR <i>ca</i>		1.00	548.00	23.00	421.96
X BRACKET,FR BUMPER,LH <i>re</i>		1.00	13.00	23.00	10.01
X BRACKET,FR BUMPER,RH <i>re</i>		1.00	13.00	23.00	10.01
X GRILLE,FR UNDER <i>de</i>		1.00	163.00	23.00	125.51

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 24/04/	Cust No/Name /NG MEIQI, JOLENE Reg No/Reg Date SMH1495C / 14/01/201 Date In/Mileage 24/04/2019/ 3873 Chassis No MMBSTA13AKH000542 Engine No 3A92UHL8706 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim U01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	06/05/2019/ 18:43		265 / AndreChow	39065
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X COVER, HEADLAMP SUPT PANEL	bt	1.00	62.00	23.00	47.74
X FACE, FR BUMPER	de	1.00	696.00	23.00	535.92
X MARK, THREE-DIA	ne	1.00	51.00	23.00	39.27
X UNPAINTED BODYKITS	ca	1.00	1110.00	20.00	888.00
X COVER, AIR CLEANER	ca	1.00	44.00	23.00	33.88

Estimate

10 days

Confirm &amp; accepted by

7% GST on	13768.66	13,768.66
		963.81
<b>Total Payable</b>		<b>14,732.47</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.