



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 24/04/	Cust No/Name /NG MEIQI, JOLENE Reg No/Reg Date SMH1495C / 14/01/201 Date In/Mileage 24/04/2019/ 3873 Chassis No MMBSTA13AKH000542 Engine No 3A92UHL8706 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim U01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	06/05/2019/ 18:43		265 / AndreChow	39065		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, RH FRONT FENDER, LH FRONT FENDER, REPAIR RH FRONT DOOR, REPAIR LH FRONT DOOR							2700.00
E PNT88000 REMOVE AND INSTALL A/CON CONDENSER AND RADIATOR TO FACILITATE REPAIR WORK							100.00
A 55900099 TOP UP A/CON GAS AND CHECK A/CON SYSTEM							80.00
E PNT98000 PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER FACE, FRONT BODY KITS, RH FRONT FENDER, LH FRONT FENDER, RH FRONT DOOR, LH FRONT DOOR AND AFFECTED PORTION							2800.00
M SUNDRY APPLY BODY SEALANT							80.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							30.00
M SUNDRY PERFORM RUST PREVENTION							80.00
M SUNDRY APPLY SEALANT FOR FRONT BODY KITS							40.00
M SUNDRY SUNDRIES							20.00
E PNT88000 VEHICLE REPAIR ON O-LINER (??) PHOTO (no photo) NAX							500.00
S SPECIALISTJOB TO SUPPLY ONE PC OF FRONT LICENSE PLATE RECTANGULAR & BLACK							50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST (REPORT) TBA							120.00
X EXC							-300.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 24/04/	Cust No/Name /NG MEIQI, JOLENE Reg No/Reg Date SMH1495C / 14/01/201 Date In/Mileage 24/04/2019/ 3873 Chassis No MMBSTA13AKH000542 Engine No 3A92UHL8706 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim U01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
KAX00008	Credit	06/05/2019/ 18:43		265 / AndreChow	39065	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
INSURANCE POLICY EXCESS						
X	PANEL ASSY,FR END	bt	1.00	1045.00	23.00	804.65
X	PANEL,HEADLAMP SUPPORT,UPR	bt	1.00	65.00	23.00	50.05
X	CONDENSER ASSY,A/C REFRIGE	bt	1.00	750.00	23.00	577.50
X	PANEL,AIR GUIDE	ca	1.00	111.00	23.00	85.47
X	RADIATOR ASSY	bt	1.00	958.00	23.00	737.66
X	TANK ASSY,RADIATOR COND	de	1.00	41.00	23.00	31.57
X	FAN,COOLING,LH		1.00	76.00	23.00	58.52
X	SHROUD,COOLING FAN	3 no photo XAN	1.00	129.00	23.00	99.33
X	LLC 4L	ne	1.00	26.00	23.00	20.02
X	PANEL,AIR GUIDE,RH	ca	1.00	11.00	23.00	8.47
X	PANEL,AIR GUIDE,LH	ca	1.00	11.00	23.00	8.47
X	CLIP,FR BUMPER	ne	10.00	3.00	23.00	23.10
X	TANK,WINDSHIELD WASHER	de	1.00	73.00	23.00	56.21
X	GASKET,W/SHLD WASHER MOTOR	ne	1.00	4.00	23.00	3.08
X	DUCT,A/CLNR INTAKE	ca	1.00	130.00	23.00	100.10
X	HOOD	bt	1.00	726.00	23.00	559.02
X	HINGE,HOOD,LH	bt	1.00	55.00	23.00	42.35
X	HINGE,HOOD,RH	bt	1.00	55.00	23.00	42.35
X	INSULATOR,HOOD	de	1.00	175.00	23.00	134.75
X	LATCH,HOOD	bt	1.00	68.00	23.00	52.36
X	CLIP,HOOD LOCKING	ne	1.00	4.00	23.00	3.08
X	CLIP,HOOD LOCKING	ne	1.00	3.00	23.00	2.31
X	FENDER,FR LH	bt	1.00	492.00	23.00	378.84
X	FENDER,FR RH	bt	1.00	492.00	23.00	378.84
X	CLIP,FENDERSHIELD	ne	10.00	3.00	23.00	23.10
X	EMBLEM ECO	ne	2.00	34.00	00.00	68.00
X	HEADLAMP ASSY,LH	ca	1.00	654.00	23.00	503.58
X	HEADLAMP ASSY,RH	ca	1.00	654.00	23.00	503.58
X	GRILLE,RADIATOR	ca	1.00	548.00	23.00	421.96
X	BRACKET,FR BUMPER,LH	ne	1.00	13.00	23.00	10.01
X	BRACKET,FR BUMPER,RH	ne	1.00	13.00	23.00	10.01
X	GRILLE,FR UNDER	de	1.00	163.00	23.00	125.51

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 24/04/	Cust No/Name /NG MEIQI, JOLENE Reg No/Reg Date SMH1495C / 14/01/201 Date In/Mileage 24/04/2019/ 3873 Chassis No MMBSTA13AKH000542 Engine No 3A92UHL8706 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim U01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	06/05/2019/ 18:43		265 / AndreChow	39065		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
X	COVER,HEADLAMP SUPT PANEL	bt		1.00	62.00	23.00	47.74
X	FACE,FR BUMPER	de		1.00	696.00	23.00	535.92
X	MARK,THREE-DIA	ne		1.00	51.00	23.00	39.27
X	UNPAINTED BODYKITS	ca		1.00	1110.00	20.00	888.00
X	COVER,AIR CLEANER	ca		1.00	44.00	23.00	33.88

Estimate

10 days

Confirm & accepted by

7% GST on	Nett	13,768.66
		963.81
Total Payable		14,732.47

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.