

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/AIS 23002763/4pa3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SL41737X

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Day 13500

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

27/3/23 1/544600 informed Allen.

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262D

PAGE 1 / 2

Estimate : 23412

Date : 14.03.2023

Vehicle Num : SLL 1737X

Make/Model : HONDA CIVIC 1.6

Chassis/Engine no :

Accident Date : 12.03.2023

Claim No : 0323-23412

Reference :

Policy No :

Qty	Particular	Amount S\$
-----	------------	------------

List Item :

1 pc	Rear boot lid	10/30f	\$672.20	1,123.20	✓
1 pc	Rear boot lock	serf	\$180.40	223.70	✓
1 pc	Rear boot lock catch	11	\$	36.80	✓
1 pc	Rear boot emblem (Civic)	ner	\$	33.10	✓
1 pc	Rear boot emblem (I vtec)	ner	\$	25.30	✓
1 pc	Rear boot centre emblem	11	\$	34.50	X
2 pc	Rear boot reflector lamp @ 325.00	11	\$	650.00	X
1 pc	Rear boot rubber	twi	\$108.40	256.30	✓
2 pc	Rear boot hinges @ 113.50	11	\$	227.00	X
1 pc	Rear boot inner board	11	\$	265.90	X
1 pc	Rear number plate lamp garnish	cre	\$	289.30	✓
2 pc	Rear number plate lamp @ 37.00	11	\$	74.00	X
2 pc	Rear fender inner garnish @ 367.80	n/s n n o/s del/tw	\$	735.60	1pc
2 pc	Rear tail lamp @ 585.00	scr/cre	321.20 x 2, 642.40	1,170.00	✓
2 pc	Rear tail lamp lower bracket @ 34.80	n/s n n o/s cre	\$	69.60	1pc
2 pc	Rear tail lamp panel @ 76.40	serf/tw	\$	152.80	✓
1 pc	Rear end panel	body	\$316.20	652.20	✓
1 pc	Rear end panel top garnish	twi	\$	71.30	✓
1 pc	Rear bumper	DD	\$617.20	780.50	✓
2 pc	Rear bumper side retainer @ 25.30	ner	\$	50.60	✓
1 pc	Rear bumper lower diffuser	del/tw	\$380	765.20	✓
1 pc	Rear bumper reinforcement	DD	\$188	372.70	✓
2 pc	Rear bumper reflector @ 42.10	11	\$	84.20	X
2 pc	Rear bumper reflector garnish @ 39.20	n/s n n o/s scr	\$	78.40	1pc
1 pc	Rear bumper parking sensor @ 235.00	no/del/tw	\$	940.00	2005/n
1 pc	Rear spare tyre panel	n	\$	1,352.20	X
1 pc	Rear spare tyre top cover board	twi	\$247.30	425.20	✓
1 pc	Rear spare tyre tool tray sponge	11	\$	256.30	X
1 pc	Rear exhaust silencer	11	\$	1,856.00	X
2 pc	Rear exhaust rubber @ 15.80	11	\$	31.60	X
List Item Total :			\$	13,083.50	
Discount 20 %			\$	2,616.70	
			\$	10,466.80	

not full work
der
16/3/23
2/s \$4600/
4 days.
take phd. After rep.

FASTECH AUTO PTE LTD

PAGE 2 / 2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262D

Estimate : 23412

Date : 14.03.2023

Vehicle Num : SLL 1737X

Make/Model : HONDA CIVIC 1.6

Chassis/Engine no :

Accident Date : 12.03.2023

Claim No : 0323-23412

Reference :

Policy No :

Qty	Particular	Amount S\$
<u>Special Nett Item :</u>		
1 pc	Rear number plate clip <i>11</i>	\$ 80.00 <i>X</i>
1 set	Rear fender inner frim clip <i>11</i>	\$ 80.00 <i>X</i>
1 set	Rear bumper clip <i>11</i>	\$ 60.00 <i>40</i>
Special Nett Item Total :		\$ 220.00
 <u>Labour Charge :</u>		
	To apply anti rust chemical	\$ 250.00 <i>80</i>
	Remove & refix cushion seat, carpet <i>11</i>	\$ 250.00 <i>80</i>
	Remove & refix exhaust pipe	\$ 120.00 <i>X</i>
	Remove & refix parking sensor	\$ 250.00 <i>50</i>
	Knock dents on front & rear damage portion, cut & welding and renew parts	\$ 1,500.00 <i>800</i>
	Respray painting	\$ 1,400.00 <i>980</i>
	Remove & refix rear w/s glass	\$ 150.00 <i>X</i>
Labour Charge Total :		\$ 3,920.00

E . & O . E

Total Amount : \$ 14,606.80

FASTECH AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-4453-1
202
7-3562-48
1-N240
1-1990
5782-48
202
4633