

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23002769/KYA3Q2
Date: 19/05/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002655167-01
Claimant Vehicle No :	SMD7532K	Insured Vehicle No :	SGY264R
Date of Loss:	07/03/2023	Nature of Claim:	TP
			Claim No: 202332006049

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD7532K		
Make & Model:	VOLKSWAGEN PASSAT B8, 1.8 TFSI AT 3G24JZ (A)	Engine No:	CJS285014
Reg. Date:	31/08/2018 (Man. Year: 2018)	Chassis No:	WVWZZZ3CZJE221738
Colour:	Metallic Blue	Odometer:	65586 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,694.20	1,361.70	5,332.50	79.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	515.00	1,885.00	78.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,094.20	1,876.70	7,217.50	79.36
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	9,094.20	1,500.00	7,594.20	83.51
+ GST 8.00/8.00% (S\$)	727.54	120.00	607.54	83.51
Nett Amount (S\$)	9,821.74	1,620.00	8,201.74	83.51
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,922.00		

INSPECTION

Date of Assignment:	16/03/2023	
Date Inspected:	23/03/2023	Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 19 May 2023)**Parts:** 143 VOLKSWAGEN PASSAT B8 1.8 TFSI AT 3G24JZ (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SMD7532K)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER	Bent	1,150.00 FL	*1,150.00 FL
2	1		*RR BUMPER RETAINER LH	Serviceable	63.00 FL	*- FL
3	1		*RR BUMPER RETAINER RH	Serviceable	63.00 FL	*- FL
4	10		*RR BUMPER CLIP	Necessary	90.00 FL	*90.00 FL
5	1		*RR BUMPER REFLECTOR LH	Cracked	58.00 FL	*58.00 FL
6	1		*RR BUMPER LOWER CHROME GARNISH	Cracked	215.00 FL	*215.00 FL
7	2		*REVERSE SENSOR	Serviceable	350.00 FL	*- FL
8	1		*RR BUMPER REINFORCEMENT	Repair	780.00 FL	*- FL
9	1		*RR END PANEL	Repair	1,420.00 FL	*- FL
10	2		*RR REINFORCEMENT BRACKET UPP LH/RH (NPA)	Not Necessary	0.00 FL	*- FL
11	2		*RR REINFORCEMENT BRACKET LOW LH/RH (NPA)	Not Necessary	0.00 FL	*- FL
12	1		*RR FENDER AIR DUCT LH	Serviceable	69.00 FL	*- FL
13	1		*TAILLAMP LH	Serviceable	540.00 FL	*- FL
14	1		*TAILGATE	Repair	2,150.00 FL	*- FL
15	1		*TAILGATE LAMP LH	Serviceable	490.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	7,438.00	1,513.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	743.80	151.30
Total Parts (\$\$)	6,694.20	1,361.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT ,WELD JACK STRAIGHTEN ,REPLACE DAMAGED PARTS & REALIGN AFFECTED AREAS	New	800.00	250.00
2	TO PUTTY ,SPRAY PAINT ON RR BUMPER ,RR END PANEL,TAILGATE ,RR FENDER LH AND AFFECTED AREAS	New	800.00	250.00
3	TO TUFF COAT ON THE AFFECTED AREAS	New	250.00	0.00
4	TO DO WHEEL ALIGNMENT	New	150.00	0.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	150.00	15.00
6	TO REMOVE & REFIT RR BUMPER REINFORCEMENT FOR RR END PANEL REPAIR	New	250.00	0.00
			Gross Labour Cost (\$\$)	515.00
			2,400.00	515.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >