

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

7P Alianz
Xiao Tony

WHEELS EXPRESS RENTAL & LEASING PTE
LTD
61 UBI AVE 2 AUTOMOBILE MEGAMART
#05-04
SINGAPORE 408898

TAX INVOICE

Repair Code : CLM17676

Date in : 19/02/2022

Vehicle Num. : SML8755K

Model : HONDA SHUTTLE HYBRID 1.5 AUTO

Chassis/Eng# : GP72003051/LEB7104036

Contact : 87773233, 81614671

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Rehnd</i>	1	1050.20	<i>965</i> 1050.20
FRONT BUMPER RH FOGLAMP <i>Neu</i>	1	287.40	<i>X</i> 287.40
FRONT BUMPER SIDE RETAINER L/R <i>RH 2nd</i>	2	14.30	<i>14.30</i> 28.60
FRONT RH CHASSIS SIDE MEMBER <i>Neu</i>	1	590.20	<i>X</i> 590.20
FRONT RH FENDER <i>Bent</i>	1	368.20	<i>✓</i> 368.20
FRONT RH FENDER 'HYBRID' EMBLEM <i>Neu</i>	1	79.20	<i>✓</i> 79.20
FRONT RH FENDER INNER SHIELD <i>Rehnd</i>	1	120.80	<i>✓</i> 120.80
FRONT RH HEADLAMP (LED) <i>Crashed</i>	1	2355.40	<i>✓</i> 2,355.40
FRONT RH HEADLAMP LOWER BRACKET <i>Neu</i>	1	45.50	<i>X</i> 45.50
Subtotal before discount			4,925.50
Percentage discount 20%			985.10
Sub-total 1			3,940.40
FRONT BUMPER CLIPS - SET <i>Neu</i>	1	80.00	<i>30</i> 80.00
FRONT RH FENDER INNER SHIELD CLIPS - SET <i>Neu</i>	1	50.00	<i>30</i> 50.00
Subtotal before discount			130.00
Percentage discount 0%			0.00
Sub-total 2			130.00
Parts-total			4,070.40

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

WHEELS EXPRESS RENTAL & LEASING PTE
LTD
61 UBI AVE 2 AUTOMOBILE MEGAMART
#05-04
SINGAPORE 408898

Contact : 87773233, 81614671

TAX INVOICE

Repair Code : CLM17676
Date in : 19/02/2022
Vehicle Num. : SML8755K
Model : HONDA SHUTTLE HYBRID 1.5 AUTO
Chassis/Eng# : GP72003051/LEB7104036

LABOUR

- To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

860

30. 60.00
400 1,000.00
400. 800.00
30. 100.00

Labour Total	1,960.00
Parts & Labour Total	6,030.40

*** This is a computer-generated document which requires no signature.***

page 2

Total: 4042.32

L/S: 3.2K.

04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: