

SCL APPRAISER PTE LTD

Vehicle Registration No.: FBN 3587 G

Our Ref No.:

GP/11/2204/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	O/s side fork tube assy (Local repair)	Damage	\$ Dent 980.00	\$ 980.00 (80) LCR
1	Front brake disc XNN	Intact	\$ 180.00	
2	Side mirrors Scr	O/S Damage	\$ 240.00	\$ 120.00 60
1	Handle bar Dent	Damage	\$ 180.00	\$ 180.00 120
1	Handle bar balancer (1 set) Scr	Damage	\$ 80.00	\$ 80.00 260
1	Hand grip (1 set) Scr	Necessary	\$ 80.00	\$ 80.00 360
1	Brake lever Scr	Damage	\$ 58.00	\$ 58.00 45
1	Front signal Scr	Damage	\$ 95.00	\$ 95.00 45
1	O/s footstep panel Cra	Damage	\$ 165.00	\$ 165.00 120
1	Exhaust pipe assy XNN	Damage	\$ 780.00	\$ 780.00
1	Exhaust protector Scr	Damage	\$ 88.00	\$ 88.00 60
2	Rear signals Scr / 135	Damage	\$ 150.00	\$ 150.00 50
1	Rear fender Scr / 181	Damage	\$ 155.00	\$ 155.00 90
1	Rear o/s footrest Scr	Damage	\$ 85.00	\$ 85.00 55
1	Rear shock absorber (1 set) Dent (Local)	Damage	\$ 800.00	\$ 800.00 (60) LCR
1	Rear fender reflector XNN	Damage	\$ 48.00	\$ 48.00
1	Rear sport rim Scr (R)	Damage	\$ 650.00	\$ 650.00
1	Rear rim bracket XNN	Damage	\$ 322.00	\$ 322.00
1	Fairing cover (1 set) Scr	Damage	\$ 1,350.00	\$ 1,350.00 300
			\$ 6,486.00	\$ 6,186.00 1005
		Less 10%	\$ 648.60	\$ 618.60 100.50
	Total Cost - List Items		\$ 5,837.40	\$ 5,567.40

SPECIAL NETT ITEMS

1	Front fender - carbon Scr	Damage	\$ 250.00	\$ 250.00 200
1	Number plate (1 set) Dent	Damage	\$ 28.00	\$ 28.00
1	Fork oil Nel	Necessary	\$ 15.00	\$ 15.00
1	Fork oil seal Nel	Necessary	\$ 28.00	\$ 28.00
1	Steering cone (1 set) XNN	Necessary	\$ 120.00	\$ 120.00
1	Air filter box cover - carbon XNN	Damage	\$ 450.00	\$ 450.00
1	Footstep side stopper XNN	Damage	\$ 48.00	\$ 48.00
	Total Cost - Special Nett Items		\$ 939.00	\$ 939.00

Total cost of parts

\$	6,776.40	\$	6,506.40
----	----------	----	----------

L APPRAISER PTE LTD

Vehicle Registration No.: FBN 3587 G

Our Ref No.:

GP/11/2204/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 6,776.40	\$ 6,506.40

LABOUR

1	To provide towing service.	\$ 50.00	\$ 50.00 30
2	To check electrical system, wire harness and focus headlamp.	\$ 80.00	\$ 50.00 30
3	To provide labour charges, workmanship to dismantle above damaged parts ; re-align body structure and damaged consistent to the accident.	\$ 480.00	\$ 400.00 280

GRAND TOTAL

\$ 7,386.40 \$ 7,006.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

$T = 1655.50$ ✓
 $\# 20/p = 331.10$
 $F7 = 1324.40$
 ≈ 1300
 $304/45$