



Blk 416 Pasir Ris Dr 6 #08-235, Singapore 510416
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Siti Nadiah Binte Azman
C/o: GP Service Pte Ltd
284 Macpherson Road,
Singapore 348608

Date : 9 January 2023
Our ref : GP/11/2204/TP

Accident Date : 21 November 2022
Inspection Date : 28 November 2022
Repairer Name : GP Service Pte Ltd
284 Macpherson Road,
Singapore 348608

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : FBN 3587 G
Make / Model : Yamaha GDR155A (Aerox)
Chassis No : MH3SG4640JJ045304
Engine No : G3J8E0056876

Year / Capacity : 2018 / 155 cc
Colour : Yellow
Mileage : 42809

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front	Pirelli	110/80 - 14	5 mm	Sport
Rear	Pirelli	140/70 - 14	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear and o/s portion.
(Details refer to the photographs attached)

Enclosed number of photographs: **111** copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$5,600.00** on a contractual basis.

Under normal circumstances, the repair period would be about 10 (Ten) working days.

Vehicle Registration No.: FBN 3587 G

Our Ref No.:

GP/11/2204/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	O/s side fork tube assy	Damage	\$ 980.00	\$ 980.00
1	Front brake disc	Intact	\$ 180.00	
2	Side mirrors	O/S Damage	\$ 240.00	\$ 120.00
1	Handle bar	Damage	\$ 180.00	\$ 180.00
1	Handle bar balancer (1 set)	Damage	\$ 80.00	\$ 80.00
1	Hand grip (1 set)	Necessary	\$ 80.00	\$ 80.00
1	Brake lever	Damage	\$ 58.00	\$ 58.00
1	Front signal	Damage	\$ 95.00	\$ 95.00
1	O/s footstep panel	Damage	\$ 165.00	\$ 165.00
1	Exhaust pipe assy	Damage	\$ 780.00	\$ 780.00
1	Exhaust protector	Damage	\$ 88.00	\$ 88.00
2	Rear signals	Damage	\$ 150.00	\$ 150.00
1	Rear fender	Damage	\$ 155.00	\$ 155.00
1	Rear o/s footrest	Damage	\$ 85.00	\$ 85.00
1	Rear shock absorber (1 set)	Damage	\$ 800.00	\$ 800.00
1	Rear fender reflector	Damage	\$ 48.00	\$ 48.00
1	Rear sport rim	Damage	\$ 650.00	\$ 650.00
1	Rear rim bracket	Damage	\$ 322.00	\$ 322.00
1	Fairing cover (1 set)	Damage	\$ 1,350.00	\$ 1,350.00
			\$ 6,486.00	\$ 6,186.00
			<i>Less 10%</i>	<i>\$ 618.60</i>
Total Cost - List Items			\$ 5,837.40	\$ 5,567.40

SPECIAL NETT ITEMS

1	Front fender -carbon	Damage	\$ 250.00	\$ 250.00
1	Number plate (1 set)	Damage	\$ 28.00	\$ 28.00
1	Fork oil	Necessary	\$ 15.00	\$ 15.00
1	Fork oil seal	Necessary	\$ 28.00	\$ 28.00
1	Steering cone (1 set)	Necessary	\$ 120.00	\$ 120.00
1	Air filter box cover - carbon	Damage	\$ 450.00	\$ 450.00
1	Footstep side stopper	Damage	\$ 48.00	\$ 48.00
Total Cost - Special Nett items			\$ 939.00	\$ 939.00

Total cost of parts

\$ 6,776.40	\$ 6,506.40
--------------------	--------------------

Vehicle Registration No.: FBN 3587 G

Our Ref No.: GP/11/2204/TP

S/No	Description	Repairer's Estimate	Revised Amount
Total cost of parts c/f		\$ 6,776.40	\$ 6,506.40
<u>LABOUR</u>			
1	To provide towing service.	\$ 50.00	\$ 50.00
2	To check electrical system, wire harness and focus headlamp.	\$ 80.00	\$ 50.00
3	To provide labour charges, workmanship to dismantle above damaged parts ; re-align body structure and damaged consistent to the accident.	\$ 480.00	\$ 400.00
GRAND TOTAL		\$ 7,386.40	\$ 7,006.40

Vehicle Registration No.: FBN 3587 G

Our Ref No.: GP/11/2204/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 5,600.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H
Automotive Appraiser

























































