



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581			Ref: CS/FCI23002777/Rny3e2 Date: 14/04/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBK 5045G	Veh. Inspected	SFG 311U	
Policy No.	D-22099191MFCV/50	Coverage (\$)	0.00	
Claim No.	D23000849MFCV	Excess (\$)	0.00	
Assign From	CAROLINE CABRERA	Assign Date	16/03/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA LEXUS RX200T EXECUTIVE 2WD	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTJZAMCA802006775	Colour	WHITE	
Odometer	134471 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/65 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	235/65 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	235/65 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	235/65 R18	BRIDGESTONE	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	08/03/2023	Inspection Date	27/03/2023	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	