

YSK AUTO

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 417883

VEHICLE DETAILS

VEHICLE NO : SNC30G
VEHICLE MODEL : HONDA CIVIC TYPE R
CHASSIS NO : SHHFN23608U300165

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Detached</i>	1	\$ 1,198.30	\$ 1,198.30
2	REAR BUMPER SIDE HOLDER <i>2nd</i>	2	\$ 36.20	\$ 72.40
3	REAR BUMPER LOWER SPOILER <i>Detached</i>	1	\$ 822.40	\$ 822.40
4	REAR BUMPER LOWER GRILLE	1	\$ 156.40	\$ 156.40
5	REAR BUMPER REINFORCEMENT <i>Detached</i>	1	\$ 392.60	\$ 392.60
6	REAR BUMPER REFLECTOR <i>3rd</i>	2	\$ 68.60	\$ 137.20
7	REAR BUMPER EXHAUST CHROME PIPE <i>3rd</i>	2	\$ 145.40	\$ 290.80
8	REAR END PANEL <i>New</i>	1	\$ 575.20	\$ 575.20
9	REAR END PANEL TOP GARNISH <i>Detached</i>	1	\$ 166.30	\$ 166.30
10	TAILLAMP <i>New</i>	2	\$ 361.60	\$ 723.20
11	TAILGATE <i>Detached</i>	1	\$ 1,257.40	\$ 1,257.40
12	TAILGATE LOCK <i>2nd</i>	1	\$ 289.40	\$ 289.40
13	TAILGATE WEATHERSTRIPE <i>at</i>	1	\$ 223.90	\$ 223.90
14	TAILGATE OUTER GARNISH <i>Detached</i>	1	\$ 1,190.50	\$ 1,190.50
15	TAILGATE INNER TRIM BOARD <i>crushed</i>	1	\$ 365.90	\$ 365.90
16	TAILGATE CENTRE GARNISH <i>new</i>	1	\$ 489.40	\$ 489.40
17	TAILGATE GLASS MOULDING <i>New</i>	1	\$ 98.40	\$ 98.40
18	HONDA LOGO <i>3 New</i>	1	\$ 58.90	\$ 58.90
19	TYPE R EMBLEM	1	\$ 68.90	\$ 68.90
20	SPARE TYRE PANEL TOP BOARD <i>3 New</i>	1	\$ 309.90	\$ 309.90
21	REAR FENDER INNER TRIM BOARD <i>3 New</i>	2	\$ 752.40	\$ 1,504.80

TOTAL PRICE: \$ 10,392.20
LESS 20% \$ 2,078.44
SUB TOTAL PRICE: \$ 8,313.76

6361.70

5089.36

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE <i>3 New</i>	1	\$ 30.00	\$ 30.00
2	REAR NUMBER PLATE HOLDER <i>3 New</i>	1	\$ 30.00	\$ 30.00
3	REAR BUMPER CLIPS <i>New</i>	1 SET	\$ 50.00	\$ 50.00
4	REAR CAMERA <i>New</i>	1	\$ 480.00	\$ 480.00
5	REAR END PANEL TOP GARNISH CLIPS <i>New</i>	1 SET	\$ 20.00	\$ 20.00
6	REAR END PANEL SEALANT <i>New</i>	1 SET	\$ 60.00	\$ 60.00
7	TAILGATE OUTER GARNISH CLIPS <i>New</i>	1 SET	\$ 30.00	\$ 30.00
8	TAILGATE INNER TRIM BOARD CLIPS <i>New</i>	1 SET	\$ 30.00	\$ 30.00
9	TAILGATE GLASS SEALANT <i>New</i>	1 SET	\$ 60.00	\$ 60.00
10	TAILGATE CENTRE GARNISH CLIPS <i>3 New</i>	1 SET	\$ 20.00	\$ 20.00
11	REAR FENDER INNER TRIM BOARD CLIPS <i>3 New</i>	2 SETS	\$ 30.00	\$ 60.00

170

TOTAL : \$ 870.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	600	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	700	
3	WIRING CHECK	\$ 50.00	30	
4	TO APPLY TUFF COAT	\$ 150.00	40	
5	TO REMOVE REAR CAMERA	\$ 100.00	50	
6	TO REMOVE UPHOLSTERY	\$ 150.00	40	
7	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	80	
8	TO REMOVE TAILGATE GLASS	\$ 180.00	120	

9 To Remove rear video recorder

100
50

TOTAL: \$ 3,180.00

1710

ESTIMATE REPORT

TOTAL PARTS COST: \$ 9,183.76

TOTAL LABOUR COST: \$ 3,180.00

TOTAL REPAIR COST: \$ 12,363.76

Total: 6969.36

h/s: S.S.K.

05 Days.

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: