



Letter of Claims

Request of direct settlement.

We are submitting a claim on behalf of our customer 604 YICK PHENG
NRIC SKXXX 105G insured of vehicle S 9N9249 against
your insured vehicle number XDJ618E. (MS First Capital
On the accident dated on 15/03/2023 (ddmmyyy) along
21 BENDI ROAD CARPARK.

Dated this 16 (day) of 03 (month) 2023.



Volkswagen Group Singapore

247 Alexandra Road

Singapore 159934

DID: 6305 7216

HP: 81214681

meiy.wong@vw.com.sg

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



SKODA

Commercial Vehicles

Quotation

Non binding - Preview

Page 1/2

Company
Ms First Capital Insurance
Limited
6 RAFFLES QUAY
#21-00
Singapore 048580

Customer Details:
Mr
GOH
YICK PHENG
BLK 142 BUKIT BATOK STREET 11
#12-05
Singapore 650142

Document no.
Document date 16-03-2023
Customer no. 5211041856
Customer GST-ID 195000106C
Dealer 30001
Job order number 2023007472/ 1
Job order date 16-03-2023
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SGN9229S	BQ13HZ	31-12-2018	WVWZZZAUZKW035529	Golf 1.4 CLBM 92 TSI D7F	51,821

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#6	280.00	302.40
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#6	480.00	518.40
5G0807217FN	Cover For Bumper Primed	1	pcs.	1,452.18	#6	1,452.18	1,568.35
5G0919493L	Sensor Bracket	1	pcs.	15.49	#6	15.49	16.73
5G0919494G	Sensor Bracket	1	pcs.	15.49	#6	15.49	16.73
5G0919493J	Sensor Bracket	2	pcs.	14.85	#6	29.70	32.08
5Q0919133 9B9	Seal Ring Satin Black	1	pcs.	1.53	#6	1.53	1.65
5Q0919275B GRU	Sensor Primed	1	pcs.	194.63	#6	194.63	210.20
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	84.64	#6	84.64	91.41
D 822150A1	Bonding Agent For Plastic	1	pcs.	74.37	#6	74.37	80.32
5G0807248G	Foam Insert	1	pcs.	73.70	#6	73.70	79.60
5G0807109AL	Impact Beam	1	pcs.	835.24	#6	835.24	902.06
	REINFORCEMENT						
5G0807049B	Guide Piece	1	pcs.	37.13	#6	37.13	40.10
	BUMPER SIDE BRACKET LH						
5G0807050B	Guide Piece	1	pcs.	37.13	#6	37.13	40.10
	BUMPER SIDE BRACKET RH						
5G0805705R	Guide	1	pcs.	85.41	#6	85.41	92.24
	BUMPER CTR BRACKET						
5G0853651CCZLL	Radiator Grille Satin Bla	1	pcs.	528.92	#6	528.92	571.23
3G0853601B DPJ	Vw Sign Black/Bright Chro	1	pcs.	106.72	#6	106.72	115.26
5G0853671G RYP	Cooling Air Grill Satin B	1	pcs.	277.89	#6	277.89	300.12
	BUMPER CTR BRACKET						
	LABOUR	3	pcs.	840.00	#6	2,520.00	2,721.60
	SPRAY PAINT	3	pcs.	800.00	#6	2,400.00	2,592.00
	FRT NUMBER PLATE	1	pcs.	80.00	#6	80.00	86.40
	INCOME ANY WS VS MS FIRST CAPITAL						
	3RD PARTY VEHICLE XD5618E						
	D.O.A: 15-03-2023						
	SURVEY BY:						

Quotation valid till 23-03-2023

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#6	760.00	8,850.17	8%	768.81	9,610.17	10,378.98
Total	760.00	8,850.17		768.81	9,610.17	10,378.98

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
Ms First Capital Insurance
Limited
6 RAFFLES QUAY
#21-00
Singapore 048580

Customer Details:
Mr
GOH
YICK PHENG
BLK 142 BUKIT BATOK STREET 11
#12-05
Singapore 650142

Document no.
Document date 16-03-2023
Customer no. 5211041856
Customer GST-ID 195000106C
Dealer 30001
Job order number 2023007472/ 1
Job order date 16-03-2023
Service Advisor YEN MEI WONG

License plate SGN9229S	Model code BQ13HZ	First registration 31-12-2018	VIN WVWZZZAUZKW035529	Model Golf 1.4 CLBM 92 TSI D7F	Mileage 51,821
---------------------------	----------------------	----------------------------------	--------------------------	-----------------------------------	-------------------

Customer



-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

All invoices are denominated in SGD, unless otherwise stated.