

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No. 133007130R GS1 Reg. No. 13-3007130-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	HSBC LIFE (SING	APORE) PTE LTD	F	Ref:	CS3/ASM22004856/Rvp3e2-1	
	C/O SEAH ONG & 36 ROBINSON RO SINGAPORE 0688	AD #12-03 CITY HOUSE		Date:	18/05/2023	
			(Code:	HSB	
1.	. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)					
	Insured Veh.	SHB 6620R	Veh. Inspected		SMF 8739P	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	23.30460	Excess (\$)		0.00	
	Assign From	HENG XINYI (SEAH ONG)	Assign Date		15/03/2023	
2. Vehicle Particulars & Condition						
	Make & Model	MAZDA 3 SEDAN 1.5 AT S/R	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	JM6BN22A8K0251102	Colour		BROWN	
	Odometer	73456 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	BRIDGESTONE		6 mm	
	L/H Front Tyre	205/60 R16	BRIDGESTONE		6 mm	
	R/H Rear Tyre	205/60 R16	BRIDGESTONE		6 mm	
	L/H Rear Tyre	205/60 R16	BRIDGESTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.					
	REPAIR CONDITION SEE DETAILS.					
5.	5. General Information					
	Accident Date	20/05/2022	Inspection Date		23/03/2023	
	Survey held at	rey held at 39 Woodlands Close #02-43, Mega @ Woodlands Singap				
	Repairer	Repairer A-TEC AUTOMOTIVE PTE LTD				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					

7 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: