

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

no full end
der
20/3/23
2/54800/
4 days

LKK Auto Consultants hereby notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE No: SKQ 1871B

1PC	BONNET	20/3/23	\$1,688.20	✓
2PCS	BONNET HINGES @\$166.00	11	\$332.00	X
1PC	BONNET INSULATOR	11	\$245.10	X
1SET	BONNET INSULATOR CLIPS	11	\$45.00	X
1PC	BONNET INNER LOCK	826	\$205.10	X
1PC	BONNET INNER LOCK CABLE	11	\$195.10	X
1PC	FRONT BUMPER	771.90	\$950.10	✓
2PCS	FRONT BUMPER SIDE RETAINERS @\$85.00	11	\$170.00	✓
1PC	FRONT BUMPER CENTRE GRILLE	771	\$388.10	✓
1PC	FRONT BUMPER SPONGE	7011	\$245.10	✓
1PC	FRONT BUMPER REINFORCEMENT	11	\$645.10	X
1PC	FRONT GRILLE	11	\$655.10	✓
1PC	FRONT GRILLE LOGO	11	\$105.00	✓
1PC	FRONT TOW COVER	11	\$38.00	X
2PCS	HEADLAMPS @\$2800.00	11	\$5,600.00	1/2
1PC	FRONT AIR GUIDE GARNISH N/S	11	\$199.10	X
1PC	FRONT SUPPORT PANEL	11	\$1,221.10	X
1PC	AIR CON CONDENSER	11	\$1,540.10	✓
1PC	RADIATOR	11	\$2,118.10	X
1PC	FRONT BRACE PANEL	11	\$151.00	✓
			\$16,736.40	

	S.NETT			
1SET	FRONT BUMPER CLIPS	11	\$50.00	✓
1PC	FRONT LICENCE PLATE W/HOLDER	11	\$50.00	40
1BOL	AIR CON OIL	11	\$50.00	30
1BOL	RADIATOR COOLANT	11	\$50.00	X

TO CHECK WIRING	\$50.00	20
TO REFILL AIR CON GAS	\$120.00	100
TO SPRAY RUST PROOFING	\$100.00	30
TO RESET & REPROGRAMME SYSTEM	\$180.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$800.00	400
TO PUTTY & SPRAY PAINTING	\$1,100.00	450
TOTAL	\$19,286.40	

6041.20

P-6562-4
252
4921.8
120
1000