

TWINCAR AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

VICTORY ENGINEERING WORKS

1084 EUNOS AVENUE 7A #01-19 EUNOS

INDUSTRIAL ESTATE

SINGAPORE 409534

TP Budget Direct.

Veron.

Contact : 87206711

TAX INVOICE

Repair Code : CLM15825

Date in : 16/03/2023

Vehicle Num. : GBD1640B

Model : NISSAN NV200 DX 1.6 AT ABS AIRBAG 2WD 5DR LGV

Chassis/Eng# : VM20055422/HR16396418C

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
CENTER PILLAR RH (CENTER) <i>Dented</i>	1	699.00	✓ 699.00
CENTER PILLAR RH (INNER) <i>Dented</i>	1	560.00	✓ 560.00
CENTER PILLAR RH (OUTER) <i>Dented.</i>	1	1659.10	<i>1295</i> 1,659.10
CENTER PILLAR RH INNER GARNISH <i>Deformed</i>	1	178.00	✓ 178.00
CENTER PILLAR RH INNER WEATHER STRIP (FRONT) <i>Not New</i>	1	169.00	✗ 169.00
CENTER PILLAR RH INNER WEATHER STRIP (REAR) <i>Not New</i>	1	169.00	✗ 169.00
CENTER PILLAR RH LOCK SWITCH <i>Damaged</i>	1	269.00	✓ 269.00
CENTER PILLAR RH PETROL LID <i>Dented</i>	1	117.60	✓ 117.60
CENTER PILLAR RH PETROL LID LOCK <i>Damaged</i>	1	78.00	✓ 78.00
CENTER PILLAR RH SEAT BELT <i>Not New</i>	1	469.00	✗ 469.00
FRONT RH DOOR <i>Distorted</i>	1	1652.80	<i>1382</i> 1,652.80
FRONT RH DOOR BLACK TAPE <i>New</i>	1	37.30	✓ 37.30
FRONT RH DOOR CHECKER <i>Best</i>	1	59.80	✓ 59.80
FRONT RH DOOR GLASS OUTER MOULDING <i>Not New</i>	1	98.50	✗ 98.50
FRONT RH DOOR GLASS REGULATOR <i>Damaged</i>	1	191.30	✓ 191.30
FRONT RH DOOR GLASS REGULATOR MOTOR <i>Damaged</i>	1	253.00	✓ 253.00
FRONT RH DOOR HINGE (LOWER) <i>Best</i>	1	67.20	✓ 67.20
FRONT RH DOOR HINGE (TOP) <i>Not New</i>	1	67.20	✗ 67.20

*** This is a computer-generated document which requires no signature.***

2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

VICTORY ENGINEERING WORKS
1084 EUNOS AVENUE 7A #01-19 EUNOS
INDUSTRIAL ESTATE
SINGAPORE 409534

Contact : 87206711

TAX INVOICE

Repair Code : CLM15825

Date in : 16/03/2023

Vehicle Num. : GBD1640B

Model : NISSAN NV200 DX 1.6 AT ABS AIRBAG 2WD 5DR LGV

Chassis/Eng# : VM20055422/HR16396418C

FRONT RH DOOR INNER RUBBER STOPPER	<i>new</i>	2	25.00	<i>+</i>	50.00
FRONT RH DOOR INNER SPONGE	<i>cracked</i>	1	68.00	<i>✓</i>	68.00
FRONT RH DOOR INNER TRIM BOARD	<i>Deformed</i>	1	504.10	<i>✓</i>	504.10
FRONT RH DOOR LOCK STRIKER	<i>new</i>	1	57.00	<i>+</i>	57.00
FRONT RH DOOR MECHANISM LOCK	<i>Damaged</i>	1	172.30	<i>✓</i>	172.30
FRONT RH DOOR OUTER HANDLE	<i>new</i>	1	78.90	<i>+</i>	78.90
FRONT RH DOOR SIDE MIRROR ASSY	<i>new</i>	1	314.00	<i>+</i>	314.00
FRONT RH DOOR WEATHER STRIP	<i>lit</i>	1	87.90	<i>✓</i>	87.90
FRONT RH FENDER	<i>new</i>	1	555.20	<i>+</i>	555.20
FRONT RH FENDER INNER SHIELD		1	107.30	<i>+</i>	107.30
FRONT RH KNUCKLE ARM	<i>Damaged.</i>	1	376.80	<i>✓</i>	376.80
FRONT RH KNUCKLE ARM BEARING		1	413.70	<i>✓</i>	413.70
FRONT RH LOWER ARM	<i>Bent</i>	1	299.60	<i>✓</i>	299.60
FRONT RH SHOCK ABSORBER		1	269.30	<i>✓</i>	269.30
FRONT RH SHOCK ABSORBER TOP MOUNTING	<i>new</i>	1	99.60	<i>+</i>	99.60
FRONT RH STABILIZER LINK	<i>new</i>	1	40.60	<i>+</i>	40.60
FRONT RH TIE ROD END		1	96.30	<i>+</i>	96.30
REAR BUMPER	<i>new</i>	1	485.90	<i>+</i>	485.90

*** This is a computer-generated document which requires no signature.***

2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

VICTORY ENGINEERING WORKS
 1084 EUNOS AVENUE 7A #01-19 EUNOS
 INDUSTRIAL ESTATE
 SINGAPORE 409534

Contact : 87206711

TAX INVOICE

Repair Code : CLM15825

Date in : 16/03/2023

Vehicle Num. : GBD1640B

Model : NISSAN NV200 DX 1.6 AT ABS AIRBAG 2WD 5DR LGV

Chassis/Eng# : VM20055422/HR16396418C

REAR BUMPER SIDE RETAINER L/R	<i>Neu</i>	2	47.30	<i>x</i>	94.60
REAR RH SLIDING DOOR	<i>Distorted</i>	1	1229.80	<i>✓</i>	1,229.80
REAR RH SLIDING DOOR CENTER HINGE WITH ROLLER	<i>Best</i>	1	98.50	<i>✓</i>	98.50
REAR RH SLIDING DOOR INNER LOCK CONTROL ASSY	<i>Damaged</i>	1	185.30	<i>✓</i>	185.30
REAR RH SLIDING DOOR INNER LOCK SWITCH	<i>Damaged</i>	1	245.00	<i>✓</i>	245.00
REAR RH SLIDING DOOR INNER LOWER WEATHER STRIP	<i>ut</i>	1	147.50	<i>✓</i>	147.50
REAR RH SLIDING DOOR INNER MECHANISM LOCK (FRONT)	<i>3 Damaged</i>	1	229.10	<i>✓</i>	229.10
REAR RH SLIDING DOOR INNER MECHANISM LOCK (REAR)		1	217.60	<i>✓</i>	217.60
REAR RH SLIDING DOOR INNER TRIM BOARD	<i>Neu</i>	1	504.10	<i>x</i>	504.10
REAR RH SLIDING DOOR LOWER HINGE WITH ROLLER	<i>Best</i>	1	98.50	<i>✓</i>	98.50
REAR RH SLIDING DOOR OUTER HANDLE	<i>3 Not Neu</i>	1	107.30	<i>x</i>	107.30
REAR RH SLIDING DOOR TOP HINGE WITH ROLLER		1	49.10	<i>x</i>	49.10
REAR RH TAILLAMP	<i>ut</i>	1	235.20	<i>✓</i>	235.20
REAR RH WHEEL BEARING	<i>Damaged</i>	1	346.10	<i>✓</i>	346.10
Subtotal before discount					14,340.70
Percentage discount 10%					1,434.07
Sub-total 1					12,906.63
FRONT RH DOOR COMPANY STICKER	<i>Neu</i>	1	25.00	<i>✓</i>	25.00

*** This is a computer-generated document which requires no signature.***

2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

VICTORY ENGINEERING WORKS
1084 EUNOS AVENUE 7A #01-19 EUNOS
INDUSTRIAL ESTATE
SINGAPORE 409534

Contact : 87206711

TAX INVOICE

Repair Code : CLM15825

Date in : 16/03/2023

Vehicle Num. : GBD1640B

Model : NISSAN NV200 DX 1.6 AT ABS AIRBAG 2WD 5DR LGV

Chassis/Eng# : VM20055422/HR16396418C

FRONT RH DOOR INNER SPEAKER	<i>cracked</i>	1	300.00	<i>180</i>	300.00
FRONT RH DOOR INNER TRIM BOARD CLIPS - SET	<i>new</i>	1	50.00	<i>30</i>	50.00
FRONT RH FENDER INNER SHIELD CLIPS - SET	<i>Not New</i>	1	50.00	<i>X</i>	50.00
FRONT RH TYRE	<i>cut</i>	1	400.00	<i>180</i>	400.00
FRONT RH WHEEL RIM		1	500.00	<i>200</i>	500.00
REAR BUMPER CLIPS - SET	<i>Not New</i>	1	80.00	<i>X</i>	80.00
REAR RH SLIDING DOOR GLASS SEAL	<i>new</i>	1	80.00	<i>30</i>	80.00
REAR RH SLIDING DOOR GLASS SEALANT	<i>685</i>	1	80.00	<i>40</i>	80.00
REAR RH SLIDING DOOR INNER TRIM BOARD CLIPS - SET	<i>Not New</i>	1	50.00	<i>X</i>	50.00
REAR RH TAILLAMP CLIPS - SET	<i>new</i>	1	25.00	<i>10</i>	25.00
REAR RH TYRE	<i>Not New</i>	1	400.00	<i>X</i>	400.00
REAR RH WHEEL RIM	<i>Ryis</i>	1	500.00	<i>X</i>	500.00
Subtotal before discount					2,540.00
Percentage discount 0%					0.00
Sub-total 2					2,540.00
Parts-total					15,446.63

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

30 ~~80.00~~

To remove, reinstall window glass. (to FR)

50 ~~150.00~~

*** This is a computer-generated document which requires no signature.***

2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

VICTORY ENGINEERING WORKS
1084 EUNOS AVENUE 7A #01-19 EUNOS
INDUSTRIAL ESTATE
SINGAPORE 409534

Contact : 87206711

TAX INVOICE

Repair Code : CLM15825

Date in : 16/03/2023

Vehicle Num. : GBD1640B

Model : NISSAN NV200 DX 1.6 AT ABS AIRBAG 2WD 5DR LGV

Chassis/Eng# : VM20055422/HR16396418C

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

220. 350.00

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

60. 200.00

To road test driving, check and resetting wheel alignments system.

80. 100.00

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

300.0

60. 100.00

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

80. 160.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

1200. 500.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

1200. 1,400.00

To apply anti-rust chemical on repaired and replaced panel.

80. 120.00

Labour Total

4,160.00

Parts & Labour Total

19,606.63

*** This is a computer-generated document which requires no signature.***

- page 5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King.
1/5 17/03/23

10 Days.

total 13125.35

1/5 10.5K

10.5K