


Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: MERCEDES BENZ A200
Engine/Chassis No.: WDD1770872J020108
Date of accident: 15.03.23
Damaged area: Rear

Date: 24/03/2023
Claim Type: TP
VRN: SMJ1223K



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper	1	\$ 1,417.00	\$ 1,417.00
2	Rear bumper reinforcement	1	\$ 983.00	\$ 983.00
3	Rear bumper side retainer	2	\$ 163.00	\$ 326.00
4	Rear bumper tow cover	1	\$ 109.00	\$ 109.00
5	Rear bumper lower	1	\$ 661.00	\$ 661.00
6	Rear bumper lower center chrome moulding	1	\$ 455.00	\$ 455.00
7	Rear bumper lower side chrome moulding	2	\$ 263.00	\$ 526.00
8	Rear bumper inner bracket upper	1	\$ 269.00	\$ 269.00
9	Rear bumper inner bracket lower	1	\$ 254.00	\$ 254.00
Subtotal				\$ 5,000.00
List discount				10.00%
Total				\$ 4,500.00

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper reverse sensor	2	\$ 180.00	\$ 360.00
2	Rear bumper sensor holder	2	\$ 28.00	\$ 56.00
3	Rear bumper clips	12	\$ 5.50	\$ 66.00
4	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 532.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	Supply spray paint material and necessary items to respray affected area / panel.	5	\$ 1,000.00
4	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,350.00
Estimate Grand Total			\$ 7,382.00