



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD 8 TEMASEK BOULEVARD, #04-01 SUNTEC TOWER THREE SINGAPORE 038988			Ref: CS/EGI23002796/Rvy3	
			Date: 17/03/2023	
			Code: EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XD 8157Z	Veh. Inspected	FBP 9170A
	Policy No.		Coverage (\$)	0.00
	Claim No.	CDMFG23000603	Excess (\$)	0.00
	Assign From	PAULINE SOH	Assign Date	17/03/2023
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	09/03/2023	Inspection Date	17/03/2023
	Survey held at	5 Soon Lee St, Pioneer Point #01-07		
	Repairer	RIGHT CLICK AUTOWORKS PTE LTD		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			