

Right Click Autoworks Pte.Ltd

493B, Bukit Batok West Ave 8, #06-965 (West Edge @ Bt Batok) S652539

UEN Reg No: 201628956M

Tel / Hp : 9149 9019

E-Mail: admin@rightclickautoworks.com.sg

To: Motor Claims Department

Date: 17/03/2023

Vehicle No: FBP9170A

Model: Yamaha Aerox

Estimated Repair Cost For FBP9170A (Yamaha Aerox)

QTY	Parts	Amount
1	Front mudguard	\$ 195.40
1	Front headlamp fairing	\$ 295.80
1	Headlamp assy	\$ 755.60
1set	Side fairing top garnish	\$ 380.90
1set	Side fairing top inner garnish	\$ 315.40
1	Handle bar	\$ 296.80
1set	Handle bar grip	\$ 128.20
1set	Handle bar balancer	\$ 150.00
1	Brake level	\$ 128.40
1set	Front fork	\$ 680.00
1	Front fork bracket	\$ 155.80
1	Front wheel	\$ 320.00
1set	Side step guard	\$ 198.60
1set	Side step guard outer garnish	\$ 255.90
1set	Side step guard lower garnish	\$ 325.40
1	Centre air-guard	\$ 128.40
1	Magnetic plate garnish n/s	\$ 296.70
1	Engine top garnish 1	\$ 128.60
1	Engine top garnish 2	\$ 255.70
1	Rider leather seat	\$ 380.50
1set	Rear side fairing	\$ 225.80
1	Rear passenger side step	\$ 79.50
1set	Rear passenger side step garnish	\$ 196.80
1	Side stand	\$ 195.60
1	Rear exhaust pipe	\$ 420.50
1set	Rear exhaust heat guard	\$ 225.80
Parts Sum:		\$ 7,116.10
Parts Less 5% :		\$ 355.80
Parts Total:		\$ 6,760.29

Special Nett Items

1set	Front Number Plate	\$ 35.00
1	Rear GRAB warmer bag	\$ 420.00
1	Rear GRAB warmer bag bracket	\$ 250.00
1set	IU unit	\$ 42.00
1	IU bracket	\$ 28.00
1set	Supply fairing sticker	\$ 280.00

Special Nett Items Total: \$ 1,055.00

Labour & Misc Charges

Description	Amount
To Remove, Replace, Re-align & Install affected Damaged Areas (\$200.00 per day)	\$ 1,000.00
To Disconnect Wire-Harness to facilitate repairs, Check & Connect Functions	\$ 80.00
To Align Body Chassis - Frame	\$ 250.00
To Replace Wheel & Balance to Specifications.	\$ 20.00
Supply Spray Paint Material & Necessary Items To Respray Affected Body & Frame	\$ 800.00
Labour Charges Total:	\$ 2,150.00

Parts Total:	\$ 6,760.29
Special Nett Items Total:	\$ 1,055.00
Labour Charges Total:	\$ 2,150.00
Total Cost Of Repair:	\$ 9,965.29
(Non-Inclusive of GST)	