

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/2PC23002806/U993

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SNJ2965J

at Workshop m/s

Rev0 performance

of

Insured:

GNG 9348

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$250k.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 85771

Veh No:

SNJ2965J

Yr Regn:

04/06/21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

RUBICON

Make:

WRANGLER UNLIMITED 1995

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

9742

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

1C4HYXMMN-8MW685981

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

37X12.50 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

BF goodrich

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

01/03/23

D.O.I.

21/3/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Rep 286

frame mounted the carrier

19-62-0317P / cost \$3733.57

12/4/23 4/5 \$6000 in brand Tony

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



REVO PERFORMANCE PTE LTD

BLK 1 KAKI BUKIT AVE 6 #02-51 & 53
SINGAPORE 417883 (AUTOBAY@KAKI BUKIT)
TEL : +65 6745 6706 FAX : +65 64843653
EMAIL : contact@revoperformance.com.sg
WEBSITE : www.revoperformance.com.sg
GST REG NO : 201200256H

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• Any item(s) must be resurveyed and
• Final approval from Insurance Company
Date:

M/S : Lonpac Insurance Bhd
100 Beach Road, #19-00
Shaw Tower Singapore 189702
TEL : 62507388
ATTN : Motor Claim Department
Your Ref No : SNJ 2965 J

Date : 20 March 2023
Policy No : MA027319
Veh Reg No : SNJ 2965 J
Make / : JEEP / WRANGLER
Model : UNLIMITED RUBICON
Chassis No : 1C4HJXMN8MW685981
Engine No : NMW685981
Reg Date : 04/06/2021

ESTIMATE REPAIR COST TO VEHICLE NO : SNJ 2965 J

NO	DESCRIPTION	U/PRICE	QUANTITY	LIST PRICE	AMOUNT
	Special Net				
1	Mopar Rear tailgate 284	\$ 3,200.00	1	\$ 3,200.00	3200
2	Rear tailgate door lock	\$ 435.00	1	\$ 435.00	17X
3	Sticker door latch & stabilizer swing gate	\$ 196.00	1	\$ 193.00	17X
4	Rear tailgate hinges top & lower	\$ 697.50	2	\$ 1,395.00	17X
5	Rear tailgate strap retaining	\$ 343.50	1	\$ 343.50	17X
6	Mopar Tailgate Reinforcement Kit	\$ 2,650.00	1	\$ 2,650.00	500X
7	Frame mounted tire carrier 3980	\$ 4,950.00		\$ 4,950.00	Best
8	Rear reverse camera 520	\$ 880.00	1	\$ 880.00	101/1000
9	Rear bumper	\$ 2,968.00	1	\$ 2,968.00	12X
				\$ 17,014.50	\$ 17,014.50
	Labour				
10	Panel beating, remove and refit rear tailgate, reinforcement kit, tire carrier, reverse camera, relocate all parts	\$ 1,200.00	1	\$ 1,200.00	600
11	Check wiring	\$ 60.00	1	\$ 60.00	20
12	To remove and replace bumper sensor	\$ 80.00	1	\$ 80.00	17X
13	To spray painting	\$ 850.00	1	\$ 850.00	300
				\$ 2,190.00	\$ 2,190.00
	TOTAL				\$ 19,204.50

TOTAL : SINGAPORE DOLLARS NINETEEN THOUSAND TWO HUNDRED FOUR AND CENTS FIFTY ONLY.

AUTHORISED SIGNATURE



1 Kaki Bukit Ave 6
#02-51 & 53 Singapore 417883
Tel: 6745 6706 Fax: 6484 3653
contact@revoperformance.com.sg
www.revoperformance.com.sg
ROC No. 201200256H

not Authorised
4/2/23
merang
21/3/23
anph
before party

1/5 & 6000