

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **AIG Asia Pacific Insurance Pte. Ltd**
78, Shenton Way,
#11-16, Singapore 079120

Attn : Motor Claims Department
Tel : 6419 3000
Fax : 6225 6772

Estimate bill : TT 17 / 23 / TP / WT

Registration No : SMD4741T

Make / model : Mazda 6

Mileage :

Date : 20 / 03 / 2023

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SMU8659H AND SMD4741T ALONG SECOND LINK EXPRESSWAY TOWARDS MALAYSIA ON 11 MARCH 2023 AT ABOUT 0700HRS.

1pc Rear bumper
4pcs 2 Rear bumper parktronic sensor
2pcs Rear bumper towing
2pcs Rear bumper reflector
Sub A total :
Less 10% discount :
A total :

(Each \$219.00) \$ Bu 1,313.00 ✓
(Each \$86.00) \$ 876.00 7
(Each \$86.00) \$ In 172.00 X
(Each \$86.00) \$ In 172.00 X
\$ 2,533.00
\$ 253.30
\$ 2,279.70

Remove and transfer rear bumper necessary attachment spart part items.

Remove and refit rear bumper, rear bumper parking sensors, rear bumper towing covers, rear bumper reflectors.

Heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Alignment jack.

Diagnostic and reset rear bumper parking sensor fault error by HHT.

To check and refit rear tail lamp wiring harness.

Under coating on rear damaged portion.

Putty / primer application, spray painting rear bumper, rear bumper parking sensors.

Grand final amount :

\$ 3,759.70

Tropical Tech Automobile Services

(Authorised Signature)
William Tan



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: