



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0269/2023/EQ
DATE : 14-Mar-23
WIP : 11911

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 17/03/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS ANG SIEW LAY
ADDRESS : BLK 615 HOUGANG AVENUE 8
#11-406
SINGAPORE 530615
TELEPHONE : HP +65 97805597
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800061143-03
VEHICLE NO : **SJQ 9301 P**
MODEL CODE : AUDI A6 1.8 TFSI S-TRONIC
MODEL YEAR : 11/6/2018
ENGINE NO : CYG 024449
CHASSIS NO : WAUZZZ4G2JN056287
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Mar-23
PLACE OF ACCIDENT : SIMS AVENUE (NEAR EUNOS MRT)

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJO 9301 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓ ✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	500 ✓
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,600.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT FENDERS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	1000 ✓
5	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT FENDER.	\$ 4,000.00	1100 ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 12,672.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJQ 9301 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Deboned</i>	1	\$ 3,677.00	✓	<i>2941.60</i>
2	FRONT BUMPER FIXING PARTS <i>He m</i>	1	\$ 602.00	+	
3	FRONT BUMPER GRILLE - LOWER CENTRE <i>He m</i>	1	\$ 151.00	+	
4	FRONT BUMPER ADAPTER - LH / RH <i>Green</i>	2	\$ 90.00	+	
5	FRONT BUMPER CLOSING ELEMENT	1	\$ 251.00	+	
6	FRONT BUMPER SPOILER <i>He m</i>	1	\$ 1,115.00	+	
7	RADIATOR GRILLE <i>could</i>	1	\$ 2,262.00	✓	<i>1809.60</i>
8	RADIATOR GRILLE COVER <i>He m</i>	1	\$ 43.00	? +	
9	FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>He m</i>	2	\$ 158.00	+	
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>Green</i>	2	\$ 1,360.00	+	
11	FRONT BUMPER CHANNEL COVER - LH / RH	2	\$ 122.00	+	
12	FRONT WHEEL SPOILER - LH / RH	2	\$ 622.00	+	
13	FRONT PARKING AID SENSOR - INNER	2	\$ 543.00	+	
14	FRONT PARKING AID SENSOR - OUTER	1	\$ 272.00	+	
15	FRONT PARKING AID SEAL RING	4	\$ 6.00	+	
16	HORN LOW TONE - LH	1	\$ 226.00	+	
17	HORN HIGH TONE - RH	1	\$ 226.00	+	
18	HORN BRACKET - LH / RH	2	\$ 112.00	+	
19	FRONT BUMPER FOAM FILLER PIECE <i>could</i>	1	\$ 280.00	? ✓	<i>224</i>
20	FRONT BUMPER SIDE REINFORCEMENT <i>He m</i>	1	\$ 983.00	? +	
SUB TOTAL SPARE PARTS			\$ 13,101.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJQ 9301 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER GUIDE PIECE - LH / RH <i>new</i>	2	\$ 89.00	<i>x</i>
22	FRONT BUMPER BRACE - LH / RH <i>new</i>	2	\$ 72.00	<i>x</i>
23	FRONT BUMPER SUPPORT - LH / RH <i>new</i>	2	\$ 31.00	<i>x</i>
24	FRONT BUMPER TOP COVER <i>rehd</i>	1	\$ 145.00	<i>✓</i> 116
25	AIR CONDITIONER STICKER <i>3 new</i>	1	\$ 24.00	<i>✓</i> 18.56
26	CAUTION SIGN STICKER	1	\$ 17.00	<i>✓</i> 13.28
27	BONNET <i>Dented</i>	1	\$ 5,861.00	<i>✓</i> 4688.80
28	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 197.00	<i>x</i>
29	BONNET HINGE - LH / RH <i>2</i>	2	\$ 382.00	<i>x</i>
30	BONNET CATCH HOOK	1	\$ 165.00	<i>x</i>
31	BONNET LOCK BAR - LH / RH <i>new</i>	2	\$ 119.00	<i>x</i>
32	BONNET CATCH HOOK <i>new</i>	1	\$ 21.00	<i>x</i>
33	BONNET LOCK - LH / RH	2	\$ 481.00	<i>x</i>
34	BONNET BOWDEN CABLE - CENTER <i>2</i>	1	\$ 67.00	<i>x</i>
35	BONNET RELEASE CABLE COVER	1	\$ 12.00	<i>x</i>
36	BONNET LOCK CABLE <i>new</i>	1	\$ 87.00	<i>x</i>
37	HEADLIGHT MOUNTING - LH / RH <i>new</i>	2	\$ 280.00	<i>x</i> 111.60
38	HEADLIGHT - LH / RH <i>RA cracked, LH cut</i>	2	\$ 21,470.00	<i>✓</i> 17176
39	LIFT CYLINDER - LH / RH <i>2 new</i>	2	\$ 548.00	<i>x</i>
40	LIFT CYLINDER HOSE	1	\$ 552.00	<i>x</i>
SUB TOTAL SPARE PARTS		:	\$ 30,620.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJQ 9301 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	HEADLIGHT WASHER COVER CAP - LH / RH <i>Not Nec</i>	2	\$ 136.00	X.
42	LOCK CARRIER <i>Not Nec</i>	1	\$ 1,470.00	+
43	OUTSIDE TEMPERATURE SENSOR BRACKET <i>Nec</i>	1	\$ 27.00	* ? X
44	A/C CONDENSER	1	\$ 878.00	+
45	CHARGE AIR COOLER	1	\$ 665.00	+
46	READY-MIX COOLANT	6	\$ 326.00	+
47	RADIATOR AIR GUIDE - LH <i>Nec</i>	1	\$ 61.00	? X
48	RADIATOR AIR GUIDE - RH <i>Nec</i>	1	\$ 276.00	? X
49	RADIATOR AIR GUIDE COVER - UPPER CENTRE <i>Nec</i>	1	\$ 34.00	? X
50	FRONT WHEEL HOUSING LINER - LH / RH <i>Nec</i>	2	\$ 670.00	X X
51	FRONT NUMBER PLATE <i>Dented.</i>	S/N	\$ 60.00	✓ 60
52	SUNDRIES <i>Nec.</i>		\$ 500.00	? ✓ 2.72
TOTAL SPARE PARTS			\$ 48,824.00	
TOTAL LABOUR CHARGES			\$ 12,672.00	
GRAND TOTAL			\$ 61,496.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ling*
SURVEYED DATE : *17/03/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *MP Authorised, 04 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT