

ASS. REC. BY:

REF:

AUG 23 002814/KP

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S14D 9577 Yr Regn: 12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) Prime Mover /

Truck / Trailer or

Make: Renault Latitude c.c. 1995Colour n. white / Red A/C: Insured / Std / NI / NASp. Reading 371036 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIFIABL15AUC 283400Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NIL / S/Rlm / STD A/Rlm orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Sailun

Front _____ Rear _____

R/Bal. 4 mm R/Bal. 5 mmL/Bal. 4 mm L/Bal. 5 mmD.O.A. 9/3/23 D.O.I. 13/3/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

14/3 21:50 @ 1550h. Car Park

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation

S + RS. \$

Fees

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL

Not Authored
1/1/2023 @ 1550h

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD957Z

AAD2303-

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

13 MAR 2023

SHD957Z

VF1ABL15AUC283400

200303878K

RENAULT

LATITUDE

9/3/2023

SJQ271B/ AIG-

29/12/2017

PART	LIST
1 BUMPER COVER REAR	\$ R 561.70 ✓
1 BUMPER BRACKET CTR REAR	\$ R 98.10 X
1 BUMPER BRACKET SIDE LH REAR	\$ L 80.80 X
1 BUMPER BRACKET SIDE RH REAR	\$ R 82.10 X
1 BUMPER RETAINER LH REAR	\$ R 54.20 X
1 BUMPER RETAINER RH REAR	\$ L 59.80 X
1 BUMPER LOWER REAR	\$ R/O 411.90 ✓
1 BUMPER BEAM REAR	\$ R 547.80 ✓
1 BUMPER BEAM BRACKET LH REAR	\$ R 114.50 X
1 BUMPER BEAM BRACKET RH REAR	\$ R 114.50 X
1 BUMPER REFLECTOR LH	\$ L 16.60 X
1 TAILLAMP LH	\$ R 401.40 X
1 OUTER PANEL REAR (End Panel)	\$ R 745.80 X
1 OUTER PANEL REAR (End Panel) TRIM	\$ L 404.56 X
1 BOOT REAR	(Br) \$ R 1,677.20 X
1 BOOT FINISHER	\$ L 344.70 X
1 BOOT LOCK	\$ R 246.60 X
1 BOOT WEATHERSTRIP	\$ L 178.20 X
1 BOOT STRUT LH	\$ L 145.10 X
1 BOOT STRUT RH	\$ L 145.10 X
1 BOOT HINGE LH	\$ R 254.20 X
1 BOOT HINGE RH	\$ R 254.20 X
1 BOOT BADGE 'RENAULT'	\$ R 82.40 X
1 BOOT BADGE	\$ R 95.80 X
TOTAL	\$ 7,117.26
25%	\$ 1,779.32
	\$ 5,337.95

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD957Z**AAD2303-****SPECIAL NETT****1SET PARKING AID**

- 1 REAR BUMPER CLIP
- 1 REAR LH BUMPER RETAINER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 REAR TAIL LAMP CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	<i>Bu</i>	700.00	X
\$	<i>nn</i>	65.00	✓
\$	<i>nn</i>	65.00	X
\$	<i>nn</i>	65.00	X
\$	<i>nn</i>	65.00	X
\$	<i>nn</i>	60.00	X
\$	<i>nn Bu</i>	180.00	<i>300</i>
\$	<i>nn</i>	150.00	X
\$	<i>nn</i>	200.00	X
\$	<i>nn</i>	130.00	X
TOTAL		\$ 1,680.00	
TOTAL PARTS		\$ 7,017.95	

LABOUR

To rust-proofing of the affected areas.	\$	<i>nn</i>	600.00	X
Putty and spray painting of the affected portion.	\$		1,200.00	<i>2201</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		2,000.00	<i>2001</i>
To transfer of tailgate fittings and conduct water seepage test.	\$	<i>nn</i>	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	X
To reinstall rear bumper parking sensor.	\$		170.00	<i>601</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i>	170.00	X

TOTAL \$ 4,910.00

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD957Z

AAD2303-

OVERALL TOTAL \$ 11,927.95

2 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: