

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No Fax No. : 62571330
 CO./ GST Reg. No. 201019626G
 SHD957Z

AAD2303-

Not Authored
1/1/2017

Vehicle No.:
 Chassis No.:
 Co UEN:
 Vehicle Make:
 Vehicle Model:
 Date of Accident:
 Third Party Insurer:
 Date of Registration:

13 MAR 2023

SHD957Z
 VF1ABL15AUC283400
 200303878K
 RENAULT
 LATITUDE
 9/3/2023
 SJQ271B/ ~~REG~~
 29/12/2017

PART

LIST

1 BUMPER COVER REAR	\$	<i>By</i>	561.70	✓
1 BUMPER BRACKET CTR REAR	\$	<i>in</i>	98.10	X
1 BUMPER BRACKET SIDE LH REAR	\$	<i>in</i>	80.80	X
1 BUMPER BRACKET SIDE RH REAR	\$	<i>in</i>	82.10	X
1 BUMPER RETAINER LH REAR	\$	<i>in</i>	54.20	X
1 BUMPER RETAINER RH REAR	\$	<i>in</i>	59.80	X
1 BUMPER LOWER REAR	\$	<i>Not/Orig</i>	411.90	✓
1 BUMPER BEAM REAR	\$	<i>By</i>	547.80	✓
1 BUMPER BEAM BRACKET LH REAR	\$	<i>in</i>	114.50	X
1 BUMPER BEAM BRACKET RH REAR	\$	<i>in</i>	114.50	X
1 BUMPER REFLECTOR LH	\$	<i>in</i>	16.60	X
1 TAILLAMP LH	\$	<i>in</i>	401.40	X
1 OUTER PANEL REAR (End Panel)	\$	<i>in</i>	745.80	X
1 OUTER PANEL REAR (End Panel) TRIM	\$	<i>in</i>	404.56	X
1 BOOT REAR	(Br) \$	<i>in</i>	1,677.20	X
1 BOOT FINISHER	\$	<i>in</i>	344.70	X
1 BOOT LOCK	\$	<i>in</i>	246.60	X
1 BOOT WEATHERSTRIP	\$	<i>in</i>	178.20	X
1 BOOT STRUT LH	\$	<i>in</i>	145.10	X
1 BOOT STRUT RH	\$	<i>in</i>	145.10	X
1 BOOT HINGE LH	\$	<i>in</i>	254.20	X
1 BOOT HINGE RH	\$	<i>in</i>	254.20	X
1 BOOT BADGE 'RENAULT'	\$	<i>in</i>	82.40	X
1 BOOT BADGE	\$	<i>in</i>	95.80	X

TOTAL \$ 7,117.26
 25% \$ 1,779.32
 \$ 5,337.95

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No Fax No. : 62571330
 CO./ GST Reg. No. 201019626G
 SHD957Z

AAD2303-

SPECIAL NETT

1SET PARKING AID

- 1 REAR BUMPER CLIP
- 1 REAR LH BUMPER RETAINER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 REAR TAIL LAMP CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	Pen	700.00	X
\$	na	65.00	✓
\$	na	65.00	X
\$	na	65.00	X
\$	na	65.00	X
\$	na	60.00	X
\$	na na	180.00	3air
\$	na	150.00	X
\$	na	200.00	X
\$	na	130.00	X
TOTAL		\$	1,680.00
TOTAL PARTS		\$	7,017.95

LABOUR

To rust-proofing of the affected areas.	\$	na	600.00	X
Putty and spray painting of the affected portion.	\$		1,200.00	22d
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		2,000.00	20u
To transfer of tailgate fittings and conduct water seepage test.	\$	na	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
To reinstall rear bumper parking sensor.	\$		170.00	60l
To check steering geometry and computer wheel alignment	\$	na	220.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	na	170.00	X
TOTAL		\$	4,910.00	

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No/Fax No. : 62571330
CO./ GST Reg. No. 2000096256
SHD957Z

AM02303

OVERALL TOTAL \$ 11,927.95

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: