

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0274/2023/EQ
DATE : 15-Mar-23
WIP : 12229

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/3/2023.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR WONG TZE YANG (HUANG ZIYANG)
ADDRESS : 80B TELOK BLANGAH ST 31
#11-121
SINGAPORE 120080
TELEPHONE : HP +65 97629938
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800028897-04
VEHICLE NO : **SLX 1728 J**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR : 28/3/2018
ENGINE NO : CVK 050814
CHASSIS NO : WAUZZZF48JA075579
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Mar-23
PLACE OF ACCIDENT : CTE (BRADDELL EXIT)

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLX 17281

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00 250	
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00 ?	
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N \$ 560.00 ✓	
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT FENDERS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	1000 (Without lock carrier) 2500 (With lock carrier)
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDER, BOTH UPPER A-PILLAR AND BOTH FRONT DOOR.	\$ 7,000.00 3300	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 15,232.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 1728 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Deformed</i>	1	\$ 2,515.00	✓
2	FRONT BUMPER FIXING PARTS <i>Not m</i>	1	\$ 641.00	+
3	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 84.00	✓
4	FRONT BUMPER GRILLE - CENTER <i>Not m</i>	1	\$ 231.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Not m</i>	1	\$ 269.00	+
6	FRONT BUMPER AIR GUIDE - LH / RH <i>Not m</i>	2	\$ 150.00	+
7	RADIATOR GRILLE <i>cracked</i>	1	\$ 1,541.00	✓
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 318.00	X
9	FRONT PARKING AID SENSOR - INNER / OUTER <i>Not m</i>	3	\$ 815.00	+
10	FRONT PARKING AID SEAL RING	4	\$ 11.00	X
11	FRONT BUMPER WIRING SET	1	\$ 573.00	X
12	HORN HIGH TONE - LH	1	\$ 142.00	X
13	HORN LOW TONE - RH	1	\$ 149.00	X
14	HORN BRACKET - LH / RH	2	\$ 70.00	+
15	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 953.00	?
16	FRONT BUMPER FOAM FILLER PIECE	1	\$ 147.00	?
17	FRONT BUMPER GUIDE SECTION - LH / RH <i>Not m</i>	2	\$ 86.00	+
18	FRONT BUMPER TOP COVER	1	\$ 151.00	?
19	CAUTION SIGN STICKER	1	\$ 17.00	?
20	AIR CONDITIONER STICKER	1	\$ 9.00	?
SUB TOTAL SPARE PARTS		:	\$ 8,872.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 1728 I

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER BRACKET ?	1	\$ 163.00	?
22	FRONT BUMPER SUPPORT - LH / RH ?	2	\$ 68.00	?
23	BONNET <i>Dented</i>	1	\$ 3,489.00	✓
24	BONNET ATTACHMENT PARTS <i>Neu</i>	1	\$ 455.00	x
25	BONNET HINGE - LH / RH <i>Neu</i>	2	\$ 722.00	x
26	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>Neu</i>	3	\$ 101.00	✓
27	BONNET STRIKER - LH / RH ?	2	\$ 120.00	?
28	BONNET LOCK - LH / RH ?	2	\$ 481.00	?
29	BONNET BOWDEN CABLE <i>Given</i>	1	\$ 67.00	x
30	BONNET RELEASE LEVER <i>Given</i>	1	\$ 16.00	x
31	BONNET BOWDEN CABLE - CENTER <i>Neu</i>	1	\$ 67.00	x
32	BONNET RELEASE CABLE COVER <i>Given</i>	1	\$ 12.00	x
33	FRONT PLENUM CHAMBER COVER <i>Given</i>	1	\$ 115.00	x
34	BONNET ENGINE SOUND ABSORBER ?	1	\$ 406.00	?
35	HEADLIGHT - LH / RH <i>LH cracked, RH ?</i>	2	\$ 17,574.00	?
36	HEADLIGHT POWER MODULE <i>2</i>	1	\$ 916.00	x
37	HEADLIGHT CONTROL UNIT	1	\$ 866.00	x
38	HEADLIGHT HOSE - LH <i>Not Neu</i>	1	\$ 43.00	x
39	LIFT CYLINDER - LH / RH	2	\$ 488.00	x
40	LIFT CYLINDER BRACKET - LH / RH	2	\$ 15.00	x
SUB TOTAL SPARE PARTS		:	\$ 26,184.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 1728 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	LIFT CYLINDER CORRUGATED PIPE <i>Not Nec</i>	1	\$ 111.00	X
42	LOCK CARRIER ?	1	\$ 1,569.00	?
43	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$ 22.00	?
44	CHARGE AIR COOLER <i>XHM</i>	1	\$ 692.00	X.
45	RADIATOR ?	1	\$ 1,103.00	?
46	A/C CONDENSER ?	1	\$ 724.00	?
47	READY-MIX COOLANT ?	6	\$ 326.00	?
48	RADIATOR AIR GUIDE - LH / RH INNER ?	2	\$ 76.00	?
49	RADIATOR AIR GUIDE - LH / RH OUTER ?	2	\$ 50.00	?
50	RADIATOR AIR GUIDE - UPPER ?	1	\$ 25.00	?
51	RADIATOR AIR GUIDE - LOWER ?	1	\$ 38.00	?
52	RADIATOR FAN RING <i>XHM</i>	1	\$ 299.00	X
53	RADIATOR FAN WITH CONTROL UNIT <i>new</i>	1	\$ 2,504.00	X
54	RADIATOR INTAKE AIR DUCT - RH ?	1	\$ 38.00	?
55	RADIATOR AIR DUCT - CENTER ?	1	\$ 67.00	?
56	RADIATOR INTAKE HOSE - UPPER ?	1	\$ 114.00	?
57	RADIATOR AIR FILTER ? <i>reheat</i>	1	\$ 443.00	?
58	FRONT WINDOW SLOT SEAL CHROME TRIM STRIP - LH / RH	2	\$ 728.00 364.	?
59	FRONT WINDOW GUIDE CHROME TRIM STRIP - LH / RH <i>reheat</i>	2	\$ 608.00	X.
60	FRONT NUMBER PLATE <i>Dented.</i>	S/N	\$ 60.00	✓
61	SUNDRIES ?		\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 45,153.00	
TOTAL LABOUR CHARGES		:	\$ 15,232.00	
GRAND TOTAL		:	\$ 60,385.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian King.
SURVEYED DATE : 17/03/23.
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 06 Days (Without Lock Carriers)
09 Days (With Lock Carriers)

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT