

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLX 1728 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00 250	
①	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00 ? 480	R.S.
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N \$ 560.00 ✓	
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT FENDERS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	1000 (Without lock carrier) 2500 (With lock carrier)
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDER, BOTH UPPER A-PILLAR AND BOTH FRONT DOOR.	\$ 7,000.00 3300	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 15,232.00	

Adrian L
 Resurveyed.
 R.S.

3
 Additional 3 days for
 replacement of condenser
 and spray painting.
 R.S.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 17281

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Deformed</i>	1	S 2,515.00	✓
2	FRONT BUMPER FIXING PARTS <i>Not New</i>	1	S 641.00	+
3	FRONT BUMPER SECURING STRIP - LH / RH	2	S 84.00	✓
4	FRONT BUMPER GRILLE - CENTER <i>Not New</i>	1	S 231.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Not New</i>	1	S 269.00	+
6	FRONT BUMPER AIR GUIDE - LH / RH <i>Not New</i>	2	S 150.00	+
7	RADIATOR GRILLE <i>crushed</i>	1	S 1,541.00	✓
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	S 318.00	X
9	FRONT PARKING AID SENSOR - INNER / OUTER <i>Not New</i>	3	S 815.00	+
10	FRONT PARKING AID SEAL RING <i>?</i>	4	S 11.00	X
11	FRONT BUMPER WIRING SET	1	S 573.00	X
12	HORN HIGH TONE - LH	1	S 142.00	X
13	HORN LOW TONE - RH	1	S 149.00	+
14	HORN BRACKET - LH / RH	2	S 70.00	+
15	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	S 953.00	✓
16	FRONT BUMPER FOAM FILLER PIECE <i>crushed</i>	1	S 147.00	✓ <i>H.S.</i>
17	FRONT BUMPER GUIDE SECTION - LH / RH <i>Not New</i>	2	S 86.00	+
18	FRONT BUMPER TOP COVER <i>crushed</i>	1	S 151.00	✓ <i>H.S.</i>
19	CAUTION SIGN STICKER <i>?</i>	1	S 17.00	✓ <i>H.S.</i>
20	AIR CONDITIONER STICKER <i>?</i>	1	S 9.00	✓ <i>H.S.</i>
SUB TOTAL SPARE PARTS		:	\$ 8,872.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 17281

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER BRACKET <i>replaced</i>	1	S 163.00	✓
22	FRONT BUMPER SUPPORT - (LH) RH <i>2H mnd</i>	2	S 68.00	✓ 34 JKS
23	BONNET <i>Dented</i>	1	S 3,489.00	✓
24	BONNET ATTACHMENT PARTS <i>Ne m</i>	1	S 455.00	X
25	BONNET HINGE - LH / RH <i>Ne m</i>	2	S 722.00	X
26	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>Ne</i>	3	S 101.00	✓
27	BONNET STRIKER - LH / RH	2	S 120.00	?
28	BONNET LOCK - LH / RH	2	S 481.00	?
29	BONNET BOWDEN CABLE <i>2</i>	1	S 67.00	X
30	BONNET RELEASE LEVER <i>2</i>	1	S 16.00	X
31	BONNET BOWDEN CABLE - CENTER <i>Ne m mnd</i>	1	S 67.00	✓
32	BONNET RELEASE CABLE COVER <i>2</i>	1	S 12.00	✓
33	FRONT PLENUM CHAMBER COVER <i>2</i>	1	S 115.00	X
34	BONNET ENGINE SOUND ABSORBER	1	S 406.00	?
35	HEADLIGHT - LH / RH <i>LH cracked, RH ?</i>	2	S 17,574.00	?
36	HEADLIGHT POWER MODULE <i>2</i>	1	S 916.00	X
37	HEADLIGHT CONTROL UNIT	1	S 866.00	X
38	HEADLIGHT HOSE - LH	1	S 43.00	X
39	LIFT CYLINDER - LH / RH	2	S 488.00	✓
40	LIFT CYLINDER BRACKET - LH / RH	2	S 15.00	✓
SUB TOTAL SPARE PARTS			\$ 26,184.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 1728 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	LIFT CYLINDER CORRUGATED PIPE <i>Not Nec</i>	1	\$ 111.00	X
42	LOCK CARRIER ?	1	\$ 1,569.00	?
43	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$ 22.00	?
44	CHARGE AIR COOLER <i>Xt m</i>	1	\$ 692.00	X.
45	RADIATOR ?	1	\$ 1,103.00	?
46	A/C CONDENSER <i>Dented</i>	1	\$ 724.00	✓ <i>h.s.</i>
47	READY-MIX COOLANT ?	6	\$ 326.00	?
48	RADIATOR AIR GUIDE - (H) RH INNER <i>LH Rehd</i>	2	\$ 76.00	38.2 <i>h.s.</i>
49	RADIATOR AIR GUIDE - (H) RH OUTER <i>RH Rehd</i>	2	\$ 50.00	25 <i>h.s.</i>
50	RADIATOR AIR GUIDE - UPPER ?	1	\$ 25.00	?
51	RADIATOR AIR GUIDE - LOWER ?	1	\$ 38.00	?
52	RADIATOR FAN RING <i>Xt m</i>	1	\$ 299.00	X
53	RADIATOR FAN WITH CONTROL UNIT <i>new</i>	1	\$ 2,504.00	X
54	RADIATOR INTAKE AIR DUCT - RH ?	1	\$ 38.00	?
55	RADIATOR AIR DUCT - CENTER ?	1	\$ 67.00	?
56	RADIATOR INTAKE HOSE - UPPER ?	1	\$ 114.00	?
57	RADIATOR AIR FILTER ? <i>rhut</i>	1	\$ 443.00	?
58	FRONT WINDOW SLOT SEAL CHROME TRIM STRIP - LH / RH	2	\$ 728.00	364
59	FRONT WINDOW GUIDE CHROME TRIM STRIP - LH / RH <i>rh</i>	2	\$ 608.00	X.
60	FRONT NUMBER PLATE <i>Dented</i>	S/N	\$ 60.00	✓
61	SUNDRIES ?		\$ 500.00	?
TOTAL SPARE PARTS			\$ 45,153.00	
TOTAL LABOUR CHARGES			\$ 15,232.00	
GRAND TOTAL			\$ 60,385.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.