

TLM Automobile Pte Ltd**1 Defu Lane 6 Singapore 539365****UEN number: 202244624K**

Ms Choo Cher Peng Catherine

Estimate To Repair

SNG313U - BMW 520i

Chassis No : WBANT12000CX30440

Third Party Insurer: MSIG Insurance

Date of accident : 15 Mar 2023

Date: 18 Mar 2023

not Authorized
her
21/3/23
L/S \$ 4600/
4 days
the 2nd after repair

S/No	Quantity	Description	Amount
LIST ITEMS			
1	1 pc	Side mirror assy LH <i>SUC</i>	\$ 685.00
2	1 pc	Side mirror cover LH <i>CUT</i>	\$ 190.00
3	1 pc	Front door LH <i>3045.00</i>	\$ 2,460.00
4	1 pc	Front door outer handle LH <i>CUT</i>	\$ 195.00
5	1 pc	Front door black sticker LH <i>her</i>	\$ 105.00
6	1 pc	Front door glass outer moulding LH <i>her</i>	\$ 225.00
7	1 pc	Front door glass run channel LH <i>11</i>	\$ 270.00
8	1 pc	Front door inner lock LH <i>11</i>	\$ 620.00
9	1 pc	Front door glass regulator LH <i>11</i>	\$ 495.00
10	1 pc	Front door glass regulator motor LH <i>11</i>	\$ 420.00
11	1 pc	Front door glass guide LH <i>11</i>	\$ 150.00
12	1 pc	Front door frame moulding LH <i>11</i>	\$ 240.00
13	1 pc	Front door insulation LH <i>11</i>	\$ 150.00
14	1 pc	Front door inner trim board LH <i>11</i>	\$ 895.00
15	1 pc	Front door inner trim board clips <i>11</i>	\$ 35.00
16	1 pc	Front door weatherstrip LH <i>her</i>	\$ 250.00
17	1 pc	Rear door LH <i>11</i>	\$ 2,450.00
18	1 pc	Rear door black sticker LH <i>her</i>	\$ 105.00
19	1 pc	Rear door lower hinge LH <i>11</i>	\$ 185.00
20	1 pc	Rear door glass regulator LH <i>11</i>	\$ 480.00
21	1 pc	Rear door glass regulator motor LH <i>11</i>	\$ 450.00
22	1 pc	Rear door weatherstrip LH <i>her</i>	\$ 255.00
23	1 pc	Side skirt garnish LH <i>11</i>	\$ 680.00
24	1 set	Side skirt garnish clips <i>11</i>	\$ 35.00
			\$ 12,025.00
Less 5%			\$ 601.25
			\$ 11,423.75

TLM Automobile Pte Ltd
1 Defu Lane 6 Singapore 539365
UEN number: 202244624K

Ms Choo Cher Peng Catherine

Third Party Insurer: MSIG Insurance

Date of accident : 15 Mar 2023

Date: 18 Mar 2023

Estimate To Repair

SNG313U - BMW 520i

Chassis No : WBANT12000CX30440

S/No	Quantity	Description	Amount
		b/f :	\$ 11,423.75
		LABOUR & MISC. CHARGES	
1		To check electrical lighting concerned.	\$ 100.00
2		To transfer of both front doors and o/s rear door fittings and perform water seepage test. @ \$120.00	\$ 240.00
3		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 200.00
4		Using onboard scan tool (OBD) perform full engine diagnostic check, to configure and clear, reset SRS service light.	\$ 200.00
5		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,200.00
6		Putty and spray painting of the affected portion.	\$ 1,400.00
7		To rust proof affected areas.	\$ 300.00
			\$ 3,640.00
		Grand Total	\$ 15,063.75

20
120
X
X
400
600
60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

p- 4790.15
52
450.64
1200
5750.64
202
4600