

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0259/2023/EQ
DATE : 11-Mar-23
WIP : 11337

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/3/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR HA HYEKUNG
ADDRESS : 50 DUCHESS AVENUE
#02-01
SINGAPORE 269196
TELEPHONE : HP +65 94554569
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220077304
VEHICLE NO : **SMP 5199 P**
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI
MODEL YEAR : 28/9/2019
ENGINE NO : DAX 054444
CHASSIS NO : WAUZZZFYSK2073805
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 9-Mar-23
PLACE OF ACCIDENT : JUNCTION OF HOLLAND ROAD AND CLUNY ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 5199 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 X.	
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. ✓ 550	\$ 2,400.00 500	✓
4	TO RESPRAY FRONT BUMPER, FRONT LOWER SPOILER, LHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS. ✓ 200+200=400	\$ 3,800.00 950	✓
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00 ✓	✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 7,552.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5199 P
DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Debond</i>	1	\$ 1,536.00	✓ 1228.80
2	FRONT BUMPER FIXING PARTS <i>Ne n</i>	1	\$ 357.00	+
3	FRONT BUMPER SECURING STRIP - LH <i>? nn</i>	1	\$ 45.00	? X
4	FRONT BUMPER CLOSING ELEMENT - LH <i>Ne n</i>	1	\$ 133.00	+
5	FRONT BUMPER SPOILER <i>{ Ne n</i>	1	\$ 900.00	+
6	FRONT BUMPER LOWER PANEL	1	\$ 260.00	+
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Ne n</i>	1	\$ 691.00	+
8	FRONT BUMPER OUTER GRILLE BAFFLE - LH <i>Ne n</i>	1	\$ 109.00	+
9	FRONT BUMPER GUIDE SECTION - LH <i>? nn</i>	1	\$ 46.00	? X
10	FRONT PARKING AID SENSOR - OUTER <i>Ne n</i>	1	\$ 272.00	+
11	FRONT PARKING AID SEAL RING <i>{</i>	4	\$ 11.00	X
12	HEADLIGHT MOUNTING - LH	1	\$ 140.00	+
13	HEADLIGHT - LH	1	\$ 9,226.00	+
14	LIFT CYLINDER - LH	1	\$ 162.00	+
15	LIFT CYLINDER HOSE <i>Stop</i>	1	\$ 150.00	+
16	FRONT FENDER - LH <i>Xler</i>	1	\$ 1,607.00	+
17	FRONT FENDER BRACE - LH	1	\$ 266.00	+
18	FRONT FENDER BRACKET - LH	1	\$ 21.00	+
19	FRONT FENDER CLOSURE PANEL - LH	1	\$ 37.00	+
20	FRONT FENDER COVER PANEL - LH	1	\$ 47.00	+
SUB TOTAL SPARE PARTS		:	\$ 16,016.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5199 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER INNER SHIELD - LH OUTER	1	\$ 93.00	X
22	FRONT WHEEL HOUSING LINER - LH	1	\$ 326.00	X
23	FRONT JOINTED SHAFT COVER - LH	1	\$ 44.00	X
24	FRONT WHEEL SPOILER	1	\$ 191.00	X
25	FRONT WHEEL COVER - LH / RH	2	\$ 1,504.00	✓ 1202.40
26	FRONT ALUMINIUM RIM - LH	1	\$ 2,153.00	✓ 1722.40
27	FRONT ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	X 3.04
28	SUNDRIES		\$ 400.00	? X
TOTAL SPARE PARTS		:	\$ 20,731.00	
TOTAL LABOUR CHARGES		:	\$ 7,552.00	
GRAND TOTAL		:	\$ 28,283.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lij*
SURVEYED DATE : *16/03/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *xbl Authorized, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT