



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23002821/Uqy3e2 Date: 30/03/2023 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKT 6011T	Veh. Inspected	SMN 6586J	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2301110/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	20/03/2023	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT (A)	c.c	1317	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GK33418712	Colour	SILVER	
Odometer	261973 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	PIRELLI	6 mm	
L/H Front Tyre	185/60 R15	PIRELLI	6 mm	
R/H Rear Tyre	185/60 R15	PIRELLI	6 mm	
L/H Rear Tyre	185/60 R15	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/03/2023	Inspection Date	20/03/2023	
Survey held at	SPEEDWERKZ PTE LTD 1 KAKI BUKIT AVE 6 #01-73, AUTOBAY @KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	