

Date: 18/03/2023

Vehicle No: SLM8048A

Model: TOYOTA PRIUS HYBRID 1.8S CVT

Chassis: JTDKB3FU703541320

Reg. Year: 2016

Third Party Insurer: INDIA

Third Party Veh No: SMP4006U

Date of Accident: 17/03/2023

Estimator: SIMON KOH

Surveyor:

Not Authorised

1/1 Pp 8

Penney Aka Rain

200MS

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER COVER	1		<i>Per</i> \$195.00
2	REAR BUMPER CENTRE GUARD	1		<i>Per/ha</i> \$220.00
3	REAR BUMPER LOWER COVER	1		<i>Per</i> \$18.00
4	REAR BUMPER REINFORCEMENT SUB ASSY	1		\$130.00
5	REAR BUMPER EXTENSION FILLER LH	1		<i>Per</i> \$55.00
6	REAR BUMPER EXTENSION FILLER RH	1		<i>Per</i> \$55.00
SUB TOTAL				\$673.00
COST +10%				\$67.30
PARTS TOTAL				\$740.30

NO.	SPECIAL NOTE	QTY	UNIT S\$	AMOUNT S\$
1	REVERSE SENSOR SET	1		\$220.00
S/N TOTAL				\$ 220.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LABOUR CHARGES:

LABOUR TO REMOVE, REPLACE/REPAIR, REALIGN & REFIX THE LISTED ACCIDENT AFFECTED PARTS.

200
\$600.00

LABOUR TO PUTTY, TOUCH UP AND RESPRAY PAINT REAR BUMPER, REAR TAILGATE AND ACCIDENT AFFECTED AREAS.

200
\$400.00

LABOUR TO CHECK, RECTIFY, REMOVE & REPLACE REAR REVERSE SENSOR SET. TO CHECK REVERSE SENSOR SYSTEM IN PROPER WORKING CONDITION.

50
\$120.00

LABOUR TOTAL \$1,120.00

SIMON TOTAL \$2,080.30