4/5/23, 7:24 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI23002825/SQY3Q2

M2301744

**Date:** 05/04/2023

**REFERENCE** 

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No:

MAA00094

923953 km

Claimant Vehicle SHD

SHD6705U

Insured Vehicle No: SLP4914K

Odometer:

Date of Loss: 16/03/2023

Nature of Claim: TP Claim No:

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHD6705U

 Make & Model:
 MERCEDES-BENZ 220E, 2.2 (A)
 Engine No:
 65192433268834

 Reg. Date:
 23/03/2016 (Man. Year: 2015)
 Chassis No:
 WDD2120012B318594

Colour: White

Engine Capacity: 2143 cc
Market Value/New Car

Price:

N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Average

**CONDITION OF TYRES** 

Front Tyre Size: 225/55 R16 Rear Tyre Size: 225/55 R16
Front Left Side: Giti 6 mm Rear Left Side: Giti 5 mm
Front Right Side: Giti 6 mm Rear Right Side: Giti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,055.92	1,747.92	1,308.00	42.80
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	980.00	680.00	300.00	30.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,046.92	2,438.92	1,608.00	39.73
Approved Total (Overridden) (S\$)		1,950.00		
(S\$)	4,046.92	1,950.00	2,096.92	51.82
+ GST 8.00/8.00% (S\$)	323.75	156.00	167.75	51.81
Nett Amount (S\$)	4,370.67	2,106.00	2,264.67	51.82

**INSPECTION** 

Date of Assignment: 20/03/2023 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 17/03/2023 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/5/23, 7:24 AM Adjuster Report

## **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Apr 2023)

Parts: 143 MERCEDES-BENZ 220E 2.2 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD6705U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Cracked	1,510.00 FL	*1,510.00 FL
2	1		*REAR BUMPER BEAM	Not Necessary	1,150.00 FL	*- FL
3	1		*REAR BUMPER BRACKET LOWER LH	Cracked	135.00 FL	*135.00 FL
4	1		*REAR BUMPER BRACKET LOWER RH	Cracked	135.00 FL	*135.00 FL
5	1		*REAR BUMPER UNDER COVER	Scratched	354.90 FL	*354.90 FL
6	1		*REAR BUMPER MAT	Necessary	50.00 FL	*50.00 FL
7	1		*REVERSE SENSOR	Not Necessary	388.00 F	*- F
F=Fra	Franchise part. L=ListItemDisc.  Sub Total (S\$)  - List Item Discount on L Items 20.00/20.00% (S\$)		<b>3,722.90</b> 666.98	<b>2,184.90</b> 436.98		
				Total Parts (S\$)	3,055.92	1,747.92

# Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount		
Misc	Miscellaneous Items						
1	1	OD/TP Case (Insurer)		11.00	11.00		
			Sub Total (S\$)	11.00	11.00		

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	500.00	400.00
2	SPRAYPAINT	New	400.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
		Gross Labour Cost (S\$)	980.00	680.00
	Report was	s unsubmitted during this print-out.		

< END OF ESTIMATES >