

N51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TP Ergo-
 Veron.

TIAN RONG TRADING
 15 YISHUN INDUSTRIAL STREET 1 #03-01
 SINGAPORE 768091

TAX INVOICE

Repair Code : CLM17681
 Date in : 13/03/2023
 Vehicle Num. : GBM669D
 Model : NISSAN NV350 CARAVAN EX AUTO
 Chassis/Eng# : VR2E26159508/QR20027480R

Contact : 98566409, 96403238

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Repair</i>	1	571.90	<i>X</i> 571.90
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	164.50	<i>+</i> 329.00
FRONT GRILLE <i>cracked</i>	1	565.00	<i>✓</i> 565.00
FRONT GRILLE 'LOGO' EMBLEM <i>new</i>	1	94.00	<i>✓</i> 94.00
FRONT RH CORNER PANEL <i>Dented</i>	1	534.60	<i>✓</i> 534.60
FRONT RH DOOR <i>Repair</i>	1	1156.00	<i>+</i> 1,156.00
FRONT RH DOOR CHECKER <i>3</i>	1	53.10	<i>+</i> 53.10
FRONT RH DOOR HINGE (LOWER) <i>new</i>	1	54.70	<i>+</i> 54.70
FRONT RH DOOR HINGE (TOP) <i>new</i>	1	54.70	<i>+</i> 54.70
FRONT RH HEADLAMP <i>cracked</i>	1	457.50	<i>✓</i> 457.50
Subtotal before discount			3,870.50
Percentage discount 10%			387.05
Sub-total 1			3,483.45
FRONT GRILLE CLIPS - SET <i>new</i>	1	30.00	<i>✓</i> 30.00
FRONT RH DOOR COMPANY DETAIL STICKER <i>new</i>	1	25.00	<i>✓</i> 25.00
FRONT RH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	30.00	<i>+</i> 30.00
FRONT RH HEADLAMP CLIPS - SET <i>new</i>	1	30.00	<i>10</i> 30.00

1651.10
 1485.99

65

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TIAN RONG TRADING
 15 YISHUN INDUSTRIAL STREET 1 #03-01
 SINGAPORE 768091

Contact : 98566409, 96403238

TAX INVOICE

Repair Code : CLM17681

Date in : 13/03/2023

Vehicle Num. : GBM669D

Model : NISSAN NV350 CARAVAN EX AUTO

Chassis/Eng# : VR2E26159508/QR20027480R

Subtotal before discount	115.00
Percentage discount 0%	0.00
Sub-total 2	115.00
Parts-total	3,598.45

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

Labour Total	1,500.00
Parts & Labour Total	5,098.45

30 80.00

X 120.00

400 200.00

300 600.00

730

Admin L
F/S 21/03/23.

04 Days

*** This is a computer-generated document which requires no signature.***

page 2

total: 2280.89.

H/s : 1.81K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: